

CAMPAIGN LAUNCH STATUS

NEW SAFETY RECALLS H294 JAGUAR XJ



RECALL H294 - RCM CALIBRATION UPDATE

AFFECTED MODELS	10-13MY AND 17MY JAGUAR XJ
VEHICLE VOLUME AFFECTED	12 USA
REPAIR	Affected vehicles require a restraints module (RCM) software update to ensure the correct deployment calibration is present in the event of a crash
REPAIR TIME	0.2 hrs + drive in/out
CAMPAIGN LAUNCH	October 1 st 2020
Notes	Retailers were notified by bulletin NAS20.09.010 on Sept 23 rd 2020