



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

September 23, 2020

Mr. J.S. (Jurassic) Park  
VP/PL & Regulatory Compliance  
Kia Motors America  
111 Peters Canyon Road  
Irvine, CA 92606-1790

NEF-150JK  
20V-560

**Subject:** Insufficient Fuel Supply

Dear Mr. Park:

This letter serves to acknowledge Kia Motors America's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

KIA/STINGER/2020-2021

**Mfr's Report Date:** September 16, 2020

**NHTSA Campaign Number:** 20V-560

**Components:**

FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP

**Potential Number of Units Affected:** 635

**Problem Description:**

Kia Motors America (Kia) is recalling certain 2020-2021 Stinger vehicles. The fuel pump's jet nozzle may have a plastic burr remaining from the manufacturing process, possibly causing a blocked nozzle and an insufficient fuel supply to the engine.

**Consequence:**

Insufficient fuel supply to the engine can result in a loss of drive power, increasing the risk of a crash.

**Remedy:**

Kia will notify owners, and dealers will inspect the fuel pump and replace the jet nozzle housing assembly, if necessary, free of charge. The recall is expected to begin October 29, 2020. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC198.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

We have received Kia's proposed owner notification letter and approved it for distribution.

Please be reminded of the following requirements:


Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at [jennifer.kruger@dot.gov](mailto:jennifer.kruger@dot.gov). We look forward to working with you.

Sincerely,



Joshua Neff  
Chief, Recall Management Division  
Office of Defects Investigations  
Enforcement