



March, 2021

**\* \* \* IMPORTANT SAFETY RECALL REMINDER \* \* \***

According to our records, your 2020 Expedition has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number**    **20S54 - Front passenger seat belt tension sensor**  
**and Description:**

**What is the issue?**            On your vehicle, the seat belt tension sensor in the seat belt buckle may have been incorrectly calibrated and may misclassify a child occupant as an adult.

In the event of a crash, the seat restraint system may enable the passenger airbag when it should be disabled, increasing the risk of an injury.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [owner.ford.com](http://owner.ford.com).

Thank you for your attention to this very important matter.

Marzo de, 2021

**\* \* \* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \* \* \***

SegUR nuestros registros, no se realizaron en sur 2020 Expedition las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:**            **20S54 - Sensor de tensión del cinturón de seguridad del pasajero delantero**

**¿Cuál es el problema?**            El sensor de tensión del cinturón de seguridad en la hebilla del cinturón de su vehículo podría haber sido mal calibrado y podría clasificar incorrectamente a un ocupante menor como un adulto.

En caso de choque, el sistema de protección del asiento podría habilitar la bolsa de aire del pasajero cuando esta debería estar desactivada, lo cual aumenta el riesgo de sufrir una lesión.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [owner.ford.com](http://owner.ford.com).

Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

B / 0950 / 000000000000036 / A



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

