



March, 2021

*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2019 F-250 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **20S56 - Dana axle tube weld**

What is the issue? On your vehicle, it may be possible the front axle tube was improperly welded during production.

During a hard braking event, drivers may experience a loud popping noise from the front axle area followed by steering effects including pulling to the right or left, changes in steering sensitivity, and mis-alignment of the steering wheel, increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: owner.ford.com.

Thank you for your attention to this very important matter.

Marzo de, 2021

*** * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * ***

SegUR nuestros registros, no se realizaron en sur 2019 F-250 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **20S56 - Soldadura de tubo de eje Dana**

¿Cuál es el problema? Es posible que en su vehículo, el tubo del eje delantero se haya soldado incorrectamente durante producción.

En una situación de frenado brusco, el conductor podría experimentar un fuerte ruido de detonación proveniente del área del eje delantero, seguido de efectos en la dirección, incluido jalón a la derecha o izquierda, cambios en la sensibilidad de la dirección y una mala alineación del volante de dirección, lo cual aumenta el riesgo de sufrir un choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: owner.ford.com.

Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

B / 0004 / 000000000000050 / A



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

