

**Recall Quarterly Report****20V-589****Manufacturer Name :** Forest River, Inc.**NHTSA Recall No. / MFR Recall No. :** 20V-589 /72-1232**Recall Subject :** Cooktop Flame May Become Inverted**Owner Notification Beginning Date :** OCT 15, 2020**Owner Notification End Date:** OCT 15, 2020

| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 3        | JUL 12, 2021    | 2021-2         | 551               | 300            | 0                 | 0             |
| 2        | APR 06, 2021    | 2021-1         | 551               | 266            | 0                 | 0             |
| 1        | JAN 18, 2021    | 2020-4         | 551               | 213            | 0                 | 0             |

This Document Last Updated : JUL 13, 2021

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.