OMB Control No.: 2127-0004

Part 573 Safety Recall Report

20V-602

Manufacturer Name: Jayco, Inc.
Submission Date: OCT 01, 2020
NHTSA Recall No.: 20V-602
Manufacturer Recall No.: 9901523



Manufacturer Information:

Manufacturer Name: Jayco, Inc.

Address: 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone: 800-283-8267

Population:

Number of potentially involved: 3 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2021-2021 Travel Trailer Jay Feather X213 "J3" Baja type

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Production records noting special build instructions

2021 Jay Feather M1J30088, 0089, 0090

Production Dates: JUN 19, 2020 - JUN 19, 2020

VIN Range 1 : Begin : NR End : NR

■ Not sequential

Description of Noncompliance:

Description of the Incorrect tire and GAWR information on labels.

Noncompliance: Labels note ST205/75R14 load range "D" and GAWR of 3,000lbs when correct

for these units is ST225/75R15 load range "E" and GAWR of 3,500lbs.

FMVSS 1: 110 - Tire selection and rims

FMVSS 2: NR

Description of the Safety Risk: Consumer may inadvertently replace tire/s with incorrect size and overload

the trailer - creating drivability issues that may result in a crash.

Description of the Cause: A special build of X213 - Baja Type travel trailer with different axles and tires

was not taken into account when noting the tire information and GAWR of the

units.

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: NR
Component Description: NR
Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: NR Address: NR NR

Country: NR

Chronology:

9-18-2020 Incident reported by Engineering as preparing set up for labels for second run of 2021 Jay Feather X213 travel trailers - Baja type - with different axles and tires - they noticed error in the label information. Investigation found error made in the first and only round of the X213 travel trailers with different axles and tires. 9-11 Incident elevated to CPAC for review - Affected units retail sold - recall is required 9-24-2020 Safety Committee reviewed and agreed that recall was required.

Description of Remedy:

Description of Remedy Program: Place new labels on affected travel trailers noting ST225/75R15 Load

range "E" tires and GAWR of 3,500lbs. Correct labels will be enclosed with the Retail Notification letter with instructions how to proceed. The current owner may take to a Jayco dealer to place the corrected labels on

the travel trailer at no charge.

How Remedy Component Differs Incorrect Labels note tires as ST205/75R14 load range "D" and the GAWR

from Recalled Component: of 3,000lbs

Identify How/When Recall Condition Data corrected by Engineering for future runs of the 2021 Jay Feather

was Corrected in Production: X213 - Baja type travel trailer.

Recall Schedule:

Description of Recall Schedule: Jayco is prepared to release recall upon assignment of Recall #

Planned Dealer Notification Date : OCT 09, 2020 - OCT 09, 2020 Planned Owner Notification Date : OCT 09, 2020 - OCT 09, 2020

Part 573 Safety Recall Report	20V-602	Page 3
* NR - Not Reported		
The information contained in this report was submitted p	oursuant to 49 CFR §573	