

Safety Recall Campaign GSX250RL8 Headlamp

Affected Models: Certain 2018 GSX250RL8 Motorcycles

Affected Departments: Management, Service, Warranty, Parts

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Suzuki Motor Corporation has decided that a defect which relates to motor vehicle safety exists in certain 2018 model-year GSX250R motorcycles.

What is the problem?

Suzuki Motor Corporation is initiating a safety recall campaign of certain 2018 GSX250R motorcycles. The filament of the headlamp bulb may fail prematurely, resulting in the headlamp going out during operation, increasing the risk of a crash.

Affected Models	Year	VIN Range
GSX250RL8	2018	LC6DN11A4J1100044 - LC6DN11A6J1102345

What is Suzuki doing to solve the problem?

Suzuki is analyzing this issue and is working to develop a repair procedure and the necessary repair parts. As soon as the procedure for inspection, repair and parts ordering becomes available, we will post this information in a Technical Service bulletin on Suzuki Connect. Suzuki will notify customers of affected motorcycles of this recall campaign on October 9, 2020.

In the meantime, if a customer brings a 2018 GSX250R to your dealership with a non-operational headlamp, please inspect the motorcycle's headlamp and replace the headlamp bulb if necessary, then submit a standard warranty request for the repair, regardless of the current warranty status of the unit.