

CAMPAIGN LAUNCH STATUS

N499 RECALL - 10 & 11MY RANGE ROVER SPORT - REAR SPOILER



SAFETY RECALL N499 REAR SPOILER UPPER COVER RETENTION	
AFFECTED MODELS	2010-2011 MY L320 Range Rover Sport
VOLUME AFFECTED	21,834 USA 1922 CAN
REPAIR	The rear spoiler cover may detach from the rear of the vehicle due to adhesive bond failure. New adhesive will be applied to the top cover. Damaged or missing spoiler covers will be replaced.
REPAIR TIME	0.5hrs for repair or 0.3hrs to replace spoiler + DIDO
CAMPAIGN LAUNCH	TBC Awaiting Parts procurement
Notes	Retailer Notification Oct 20 th 2020 - Bulletin NAS20.10.016. Customers have received an interim notification letter.