



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

October 20, 2020

Mr. Greg Gunther
Department Manager VCA
Mercedes-Benz USA, LLC.
13470 International Parkway
Jacksonville, FL 32218

NEF-150JK
20V-627

Subject: Locking Ring Connection on Drive Shaft May Fail

Dear Mr. Gunther:

This letter serves to acknowledge Mercedes-Benz USA, LLC.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MERCEDES-BENZ/GLE350/2020

Mfr's Report Date: October 9, 2020

NHTSA Campaign Number: 20V-627

Components:

POWER TRAIN:DRIVELINE:DRIVESHAFT

Potential Number of Units Affected: 2

Problem Description:

Mercedes-Benz USA LLC. (MBUSA) is recalling certain 2020 GLE 350 vehicles. The connection of the locking ring between the front and rear part of the drive shaft might not have been installed correctly, possibly resulting in a loss of power transfer between the transfer case and the rear axle differential.

Consequence:

If the transfer case disconnects from the rear axle differential the vehicle could stall, increasing the risk of a crash.

Remedy:

MBUSA will notify owners, and dealers will replace the drive shaft, free of charge. The recall is expected to begin December 8, 2020. Owners may contact MBUSA customer service at 1-800-367-6372.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov. We look forward to working with you.

Sincerely,



Joshua Neff
Chief, Recall Management Division
Office of Defects Investigations
Enforcement