

Recall Quarterly Report**20V-633**

Manufacturer Name : Toyota Motor Engineering & Manufacturing
NHTSA Recall No. / MFR Recall No. : 20V-633 /20TB14 / 20TA14
Recall Subject : Seat Trim Can Interfere with Air Bag Deployment
Owner Notification Beginning Date : DEC 11, 2020
Owner Notification End Date: DEC 11, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JUL 27, 2021	2021-2	3,121	2,600	47	3
2	APR 21, 2021	2021-1	3,121	2,280	47	2
1	JAN 26, 2021	2020-4	3,121	1,253	0	4

This Document Last Updated : JUL 29, 2021

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.