

SAFETY RECALL 20TA14

There is a possibility that one or both of the front seats were equipped with an incorrect trim cover. If these trim covers are incorrect, the cover could prevent the seat-mounted side air bag from deploying properly when the air bags are commanded to deploy, increasing the risk of injury in the event of a crash.

Please call your dealer ASAP to schedule a FREE repair. For more information, please visit Toyota.com/recall.