OMB Control No.: 2127-0004

Recall Quarterly Report

20V-655

Manufacturer Name: Forest River, Inc.

NHTSA Recall No. / MFR Recall No.: 20V-655 /15-1245
Recall Subject: Furnace Fresh Air Intake Sleeve Too Short
Owner Notification Beginning Date: NOV 06, 2020

Owner Notification End Date: NOV 06, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JUL 12, 2021	2021-2	69	34	0	0
2	APR 06, 2021	2021-1	69	25	0	0
1	JAN 18, 2021	2020-4	69	10	0	0

This Document Last Updated: JUL 13, 2021

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.