



KEYSTONE
RV COMPANY

RECREATIONAL VEHICLE
SAFETY RECALL NOTICE

Safety Recall: 20V-670
Safety Advisory: 20-389
Transport Canada: 2020-526
November 18, 2020

Recall Population

2020 – 2021 Cougar Fifth Wheel and Travel Trailers

Models: 22RBSWE, 24SABWE, 25BHSWE, 26RBSWE, 27RESWE, 27SABWE, 29BHSWE, 29RLDWE, 29RLKWE, 29RLSWE, 30RKDWE, 31BHKWE, 32RDBWE, 24RDS, 25RES, 27SGS, 29MBS, 29RKS, 302RLS, 307RES, 30RLS, 315RLS, 316RLS, 32BHS, 353SRX, 364BHL, 366RDS, 367FLS, 368MBI, 361RLW

Serial Number Ranges:

2020 L2502429 - L2509218

LC503863 - LC509167

2021 M2500058 - M2505320

MC500000 - MC502509

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in the vehicles listed above. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

***Reason for
this recall***

It has been decided that the vehicles in the recall population have an inverter that may have been incorrectly wired and when in use, is allowing power to energize the shore power connection. When the incorrectly wired inverter is turned on, 120VAC power will energize the shore power connection leading to an increased risk of personal injury.

***What we
will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is test the function of the inverter and rewire as needed. The service and parts required for this corrective action will be provided at no charge to you.

***What we
need you to
do***

If the inverter is turned on and any circuits other than the “Off The Grid Inverter Outlet” circuit is powered on then turn off the inverter and have the system inspected by an authorized dealer. As soon as possible, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately 1 hour. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

***If you have
questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. Please contact Keystone Customer service if your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you. You may be eligible to receive reimbursement if you paid to have the defect resolved prior to receiving this correspondence. Keystone Customer Service is available toll-free at 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.)

PO Box 2000 – Goshen, IN 46527-2000
Phone: (574) 535-2100 – Fax: (574) 535-2199
www.keystonerv.com

