



# Parts Bulletin

**TITLE:**

**Recall R10058: Drivers Airbag  
Model Year S60 2001-2003, S80 2001-2003**

**GROUP:  
88**

**CAT/NO:  
R10058**

**CAR MARKET:  
United States**

**REVISIONS:**

**ISSUE DATE:  
2021-04-21**

**STATUS DATE:  
2021-04-21**

**Page 1 of 3**

**“Right first time in Time”**

## Reference Bulletins: QB 10058

Volvo Car USA LLC on behalf of Volvo Car Corporation, has decided to launch Recall R10058 on model year 2001 – 2003 S60 Series and S80 Series vehicles.

Volvo has identified that in the event of a crash with a driver airbag activation, the propellant inside the driver airbag may cause the airbag to rupture. This condition could render the driver to be struck by fragments of metal from the inflator.

The corrective action is to replace the Driver Airbag.

A total of 54,124 U.S. vehicles are eligible for this recall.

At this time parts are **only available for the S60 Series vehicles**. In January 2021, a notice was mailed to all involved customers that Volvo had decided that a defect which relates to motor vehicle safety exists in certain 2001-2003 model year S60 vehicles and that replacement parts needed to perform the final repair were not available. A second notice informing all involved customers was mailed on April 21, 2021 informing that these parts are now available. Due to supply limitations, the color of the replacement airbag will only be available in gray-charcoal. Parts for the S80 MY01-03 will not be available until a later date.



Example:

Light colored Interior



New airbag charcoal



It is imperative that **NO AIRBAGS ARE DETONATED/DEPLOYED** once removed from the vehicle. VIDA may instruct the technicians to do so but detonating the airbag should not be done. Defective parts will be required to be sent back to Volvo for disposal. Please hold on to all air bags until a parts return process is communicated.



### Caution!

Handle all the packaging with care, this shall be re-used when returning the old component.

- Cardboard box
- Steel cage
- Wrapping material

**IMPORTANT:** The Serial Number of the NEW Airbag, and only the serial number, must be entered on the first line of the Warranty Claim “Repair Text”. Claims for Recall R10058 will not be required to follow Volvo’s published Repair Text requirements. The Volvo Personnel ID number should not be included. **Do not add any additional text, figures or comments.** If the NEW serial number is not provided on the first line of the repair text the claim will be rejected. It must also be noted on the **Repair Order hardcopy**.



The following part numbers apply:

Part Number	Description	Qty
32332161 (S60 ONLY)	Airbag	1