



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

November 27, 2020

Mr. Appie Theron
Autocar, LLC
551 S Washington Street
Hagerstown, IN 47346

NEF-150MR
20V-687

Subject: Engine Ground Cable Too Short And May Fail

Dear Mr. Theron:

This letter serves to acknowledge Autocar, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

AUTOCAR/XPEDITOR/2020-2021

Mfr's Report Date: November 6, 2020

NHTSA Campaign Number: 20V-687

Components:

ENGINE

Potential Number of Units Affected: 116

Problem Description:

Autocar, LLC (Autocar) is recalling certain 2020-2021 Xpeditor vehicles equipped with X12N engines. The engine ground cable is too short and may fail.

Consequence:

If the ground cable fails, the engine may stall without the ability to restart, and increase the risk of a crash or injury.

Remedy:

Autocar will notify owners and dealers will replace the ground cable, free of charge. The recall is expected to begin January 4, 2021. Owners can contact Autocar customer service at 1-888-218-3611 or 1-877-973-3486. Autocar's number for this recall is ACX-2007.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:




You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Joshua Neff
Chief, Recall Management Division
Office of Defects Investigations
Enforcement