



**IMPORTANT SAFETY RECALL**

**AUTOCAR, LLC SAFETY RECALL ACX-2008  
NHTSA RECALL NO. 20V689**

**January 2021**

**TO:** U.S. Distributors  
Dealer Principals, Service Managers, Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar, LLC has determined that a defect, which relates to motor vehicle safety, exists in 1060, 2020-2021 model year Xpeditor and Legend chassis. The Xpeditor chassis were manufactured between September 16, 2019 and August 30, 2020 with non-sequential serial numbers between 231681 and 234498 and the Legend chassis were manufactured between October 11, 2019 and July 30, 2020, accordingly, a recall to address this issue is being initiated effective January 4, 2021.

**MODELS** Autocar Xpeditor and Legend MY 2020-2021

**AFFECTED:**

**COMPONENTS** Transverse Torque Rod Mounting Bolts.

**AFFECTED:**

**SAFETY DEFECTS AND POTENTIAL RISKS:** If the transverse torque rod mounting bolts are not properly torqued, the bolts could fail and become disconnected from the vehicle, increasing the risk of a crash, personal injury or property damage.

**REPAIR REQUIRED:** The transverse torque rod mounting bolts will be properly torqued at no charge to the owner.

**REPAIR AVAILABLE:** VIN profiles in the Autocar Warranty System will be updated to show the open recall on January 5, 2021 and a spreadsheet of the affected VINs will be available in the Warranty system.

**REMINDER:** It is a violation of Federal law to sell or lease a vehicle covered by this recall notice unless the recall remedy has been completed. Substantial civil penalties apply to violations of this law.

If you have any questions or concerns, please contact the Autocar Warranty Department at [warranty@autocartruck.com](mailto:warranty@autocartruck.com).

Sincerely,

**AUTOCAR, LLC**

ACF 00002 Rev. 000