



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

November 20, 2020

Ms. Helen Riehle
Safety Integrity and Recall Manager
BMW of North America, LLC
300 Chestnut Ridge Road
Woodcliff Lake, NJ 07677

NEF-150DM
20V-700

Subject: Fuel Tank Weld May Fail

Dear Ms. Riehle:

This letter serves to acknowledge BMW of North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BMW/Z4/2020-2021
TOYOTA/SUPRA/2020-2021

Mfr's Report Date: November 12, 2020

NHTSA Campaign Number: 20V-700

Components:

FUEL SYSTEM, GASOLINE:STORAGE:TANK ASSEMBLY

Potential Number of Units Affected: 49

Problem Description:

BMW of North America, LLC (BMW) is recalling certain 2020-2021 Z4 and 2020-2021 Toyota Supra vehicles. The weld between the fuel tank halves may not have been performed to specifications, and could cause the weld to fail over time.

Consequence:

A failed weld may allow fuel to leak, increasing the risk of a fire in the presence of an ignition source.

Remedy:

BMW will notify owners, and dealers will replace the fuel tank, free of charge. The recall is expected to begin January 4, 2021. Owners may contact BMW customer service at 1-800-525-7417 or Toyota customer service at 1-888-270-9371.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be DeMara Magruder who may be reached by phone at (202) 366-8538, or by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,



Joshua Neff
Chief, Recall Management Division
Office of Defects Investigations
Enforcement