

**Recall Quarterly Report****20V-709****Manufacturer Name :** Tesla, Inc.**NHTSA Recall No. / MFR Recall No. :** 20V-709 /SB-20-31-012**Recall Subject :** Loose Control Arm Bolts May Affect Steering**Owner Notification Beginning Date :** JAN 15, 2021**Owner Notification End Date:** JAN 15, 2021

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JUL 29, 2021	2021-2	401	327	0	0
1	APR 30, 2021	2021-1	401	314	0	0

This Document Last Updated : JUL 29, 2021

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.