Recall Quarterly Report

20V-709

Manufacturer Name : Tesla, Inc. NHTSA Recall No. / MFR Recall No. : 20V-709 /SB-20-31-012 Recall Subject : Loose Control Arm Bolts May Affect Steering Owner Notification Beginning Date : JAN 15, 2021 Owner Notification End Date: JAN 15, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 30, 2021	2021-1	401	314	0	0

This Document Last Updated : MAY 06, 2021

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.