

TOPIC	TYPE	RECALL CODE	QUESTION	ANSWER			
Safety Recall 69BH	Safety Recall	69BH	What vehicles are included in Safety Recall 69BH?				
				Country	Beginning Model Year	Ending Model Year	Vehicle
				USA	2018	2018	TIGUAN
			What is the safety concern for Safety Recall 69BH?	During two (2) NHTSA New Car Assessment Program (NCAP) tests, the seat belts on the front driver side of the Tiguan ruptured. A ruptured seat belt may increase the risk of injuries in the event of a vehicle crash.			
			What is the repair for Safety Recall 69BH?	Your authorized Volkswagen dealer will replace one or both front seat belts.			
			When will the repair for Safety Recall 69BH be available?	Parts are available now and repairs have begun. Please contact your authorized Volkswagen dealer without delay to schedule this recall repair. To set up an appointment online, please visit www.vw.com/find-a-dealer .			