

Part 573 Safety Recall Report

20V-727

Manufacturer Name : Forest River, Inc.**Submission Date :** NOV 23, 2020**NHTSA Recall No. :** 20V-727**Manufacturer Recall No. :** 51-1259**Manufacturer Information :****Population :**

Manufacturer Name : Forest River, Inc.

Number of potentially involved : 3,875

Address : 55470 CR 1

Estimated percentage with defect : 100 %

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Vehicle Information :

Vehicle 1 : 2019-2021 Coachmen Concord CNC300DSC, CNC300DSF, CSN300TSF

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : On November 17, 2020, OCC received clarification to the report delivery dates and began to identify those vehicles involved at the known manufacturing plants. OCC is still working with Dometic to identify deliveries in which Dometic cannot assign a physical address, which means OCC does not know which manufacturing plant(s) other than what is recalled, is affected. At this time, Dometic is working to supply OCC with this information.

On November 18, 2020, OCC received via USPS Mail formal notification to Forest River of Dometic Recall 20E071. OCC is still trying to identify other manufacturing plants received the subject stoves/cooktops.

CONCORD	CNC300DSC	2019	3
CONCORD	CNC300DSC	2020	2
CONCORD	CNC300DSF	2019	25
CONCORD	CNC300DSF	2020	38
CONCORD	CNC300TSF	2019	8
CONCORD	CNC300TSF	2020	6

Production Dates : AUG 29, 2018 - APR 17, 2020**VIN Range 1 : Begin :**

NR

End : NR☐ Not sequential

Vehicle 2 : 2019-2021 Coachmen Cross Trek C1C20XGT, C1C27XGF35

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : On November 17, 2020, OCC received clarification to the report delivery dates and began to identify those vehicles involved at the known manufacturing plants. OCC is still working with Dometic to identify deliveries in which Dometic cannot assign a physical address, which means OCC does not know which manufacturing plant(s) other than what is recalled, is affected. At this time, Dometic is working to supply OCC with this information.

On November 18, 2020, OCC received via USPS Mail formal notification to Forest River of Dometic Recall 20E071. OCC is still trying to identify other manufacturing plants received the subject stoves/cooktops.

CROSS TREK C1C20XGT 2020 14

CROSS TREK C1C27XGF35 2020 1

Production Dates : AUG 29, 2018 - APR 17, 2020

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 3 : 2019-2021 Forest River Inc. Dynamax DX3-DXC37TS, Dynaquest XL-DLC37BH, DYNAQUEST XL-DLC3801TS, FORCE-FRC334KDHD, FRC37BHHD, FRC37TSHD, ISATA ISC30FWD, ISC30FWD4X4, ISC36DSD, ISSC36D4X4

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : On November 17, 2020, OCC received clarification to the report delivery dates and began to identify those vehicles involved at the known manufacturing plants. OCC is still working with Dometic to identify deliveries in which Dometic cannot assign a physical address, which means OCC does not know which manufacturing plant(s) other than what is recalled, is affected. At this time, Dometic is working to supply OCC with this information.

On November 18, 2020, OCC received via USPS Mail formal notification to Forest River of Dometic Recall 20E071. OCC is still trying to identify other manufacturing plants received the subject stoves/cooktops.

DYNAMAX DX3	DXC37TS	2020	2
DYNAQUEST XL	DLC37BH	2020	2
DYNAQUEST XL	DLC3801TS	2020	1
FORCE FRC34KDHD	2020	3	
FORCE FRC37BHHD	2020	1	
FORCE FRC37TSHD	2020	1	
ISATA ISC30FWD	2020	2	
ISATA ISC30FWD4X4	2020	3	
ISATA ISC36DSD	2020	1	
ISATA ISC36DSD4X4	2020	2	

Production Dates : AUG 29, 2018 - APR 17, 2020

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 4 : 2019-2021 Coachmen Freelanders - AFLC21QBC AFLC21QBF35 FLC20CBT FLC21QBC
FLC21QBF35 FLC21RSC FLC21RSF35 FLC22XGC FLC22XGF35 FLC23FSC
FLC23FSF35 FLC24FSC FLC24FSF45 FLC26DSC FLC26DSF45 FLC26RSC FLC26RSF35
FLC27QBC FLC27QBF35 FLC28SSF45 FLC29KBF45 FLC30BHF45 FLC31BHF45

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information :	FREELANDER	AFLC21QBC	2020	57
	FREELANDER	AFLC21QBF35	2020	6
	FREELANDER	FLC20CBT	2020	5
	FREELANDER	FLC21QBC	2019	36
	FREELANDER	FLC21QBC	2020	45
	FREELANDER	FLC21QBC	2021	6
	FREELANDER	FLC21QBF35	2019	4
	FREELANDER	FLC21QBF35	2020	8
	FREELANDER	FLC21RSC	2019	13
	FREELANDER	FLC21RSC	2020	25
	FREELANDER	FLC21RSF35	2019	4
	FREELANDER	FLC21RSF35	2020	13
	FREELANDER	FLC22XGC	2020	30
	FREELANDER	FLC22XGF35	2020	2
	FREELANDER	FLC23FSC	2020	32
	FREELANDER	FLC23FSF35	2020	3
	FREELANDER	FLC24FSC	2019	3
	FREELANDER	FLC24FSC	2020	13
	FREELANDER	FLC24FSF45	2019	1
	FREELANDER	FLC24FSF45	2020	7
	FREELANDER	FLC26DSC	2019	17
	FREELANDER	FLC26DSC	2020	40
	FREELANDER	FLC26DSF45	2019	8
	FREELANDER	FLC26DSF45	2020	11
	FREELANDER	FLC26RSC	2019	9
	FREELANDER	FLC26RSC	2020	26
	FREELANDER	FLC26RSF35	2019	2
	FREELANDER	FLC26RSF35	2020	10
	FREELANDER	FLC27QBC	2019	80
	FREELANDER	FLC27QBC	2020	154
	FREELANDER	FLC27QBC	2021	6
	FREELANDER	FLC27QBF35	2019	7
	FREELANDER	FLC27QBF35	2020	25
	FREELANDER	FLC28SSF45	2019	15
	FREELANDER	FLC28SSF45	2020	36
	FREELANDER	FLC29KBF45	2020	7
	FREELANDER	FLC30BHF45	2020	16
	FREELANDER	FLC30BHF45	2021	6
	FREELANDER	FLC31BHF45	2019	6
	FREELANDER	FLC31BHF45	2020	87
	FREELANDER	FLC31FSF45	2020	2
	FREELANDER	FLC31MBF45	2020	23
	FREELANDER	FLC32DSF45	2019	50
	FREELANDER	FLC32DSF45	2020	37

Vehicle 5 : 2019-2021 Coachmen Orion - RNC20CBFT RNC21RSFT RNC24CB

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : On November 17, 2020, OCC received clarification to the report delivery dates and began to identify those vehicles involved at the known manufacturing plants. OCC is still working with Dometic to identify deliveries in which Dometic cannot assign a physical address, which means OCC does not know which manufacturing plant(s) other than what is recalled, is affected. At this time, Dometic is working to supply OCC with this information.

On November 18, 2020, OCC received via USPS Mail formal notification to Forest River of Dometic Recall 20E071. OCC is still trying to identify other manufacturing plants received the subject stoves/cooktops.

ORION RNC20CBFT	2019	6
ORION RNC20CBFT	2020	22
ORION RNC21RSFT	2020	1
ORION RNC21TBFT	2020	2
ORION RNC24CB	2019	8
ORION RNC24CB	2020	6
ORION RNC24RB	2019	2
ORION RNC24RB	2020	5

Production Dates : AUG 29, 2018 - APR 17, 2020

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential

Vehicle 6 : 2019-2021 Coachmen Prism - PRC2150CB PRC2200FS PRC2250DS PRC2300DS
PRC24EE PRC24EF PRC24EG PRC24EJ

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : On November 17, 2020, OCC received clarification to the report delivery dates and began to identify those vehicles involved at the known manufacturing plants. OCC is still working with Dometic to identify deliveries in which Dometic cannot assign a physical address, which means OCC does not know which manufacturing plant(s) other than what is recalled, is affected. At this time, Dometic is working to supply OCC with this information.

On November 18, 2020, OCC received via USPS Mail formal notification to Forest River of Dometic Recall 20E071. OCC is still trying to identify other manufacturing plants received the subject stoves/cooktops.

PRISM	PRC2150CB	2019	18
PRISM	PRC2150CB	2020	11
PRISM	PRC2200FS	2019	54
PRISM	PRC2200FS	2020	28
PRISM	PRC2250DS	2019	2
PRISM	PRC2300DS	2019	41
PRISM	PRC2300DS	2020	16
PRISM	PRC24EE	2020	4
PRISM	PRC24EF	2019	18
PRISM	PRC24EF	2020	11
PRISM	PRC24EG	2019	1
PRISM	PRC24EJ	2019	3
PRISM	PRC24EJ	2020	1

Production Dates : AUG 29, 2018 - APR 17, 2020

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 7 : 2019-2021 Coachmen Pursuit - PSA27DSPF PSA27XPSF PSA29SSPF PSA31BHF
PSA31TSF PSA32WCPF

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : On November 17, 2020, OCC received clarification to the report delivery dates and began to identify those vehicles involved at the known manufacturing plants. OCC is still working with Dometic to identify deliveries in which Dometic cannot assign a physical address, which means OCC does not know which manufacturing plant(s) other than what is recalled, is affected. At this time, Dometic is working to supply OCC with this information.

On November 18, 2020, OCC received via USPS Mail formal notification to Forest River of Dometic Recall 20E071. OCC is still trying to identify other manufacturing plants received the subject stoves/cooktops.

PURSUIT	PSA27DSPF	2020	3
PURSUIT	PSA27XPSF	2020	41
PURSUIT	PSA29SSPF	2020	7
PURSUIT	PSA31BHF	2020	1
PURSUIT	PSA31TSF	2020	9
PURSUIT	PSA32WCPF	2020	1

Production Dates : AUG 29, 2018 - APR 17, 2020

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 8 : 2019-2021 Coachmen Leprechaun - LPC200CBF8RB9-215 LPC210QBC
LPC210QBF35 LPC210RSC LPC210RSF35 LPC220QBF8RB9 LPC220QBF8RB9-215
LPC220XGC LPC230CBF8RB9 LPC230FSC LPC230FSF35 LPC240FSC LPC240FSF
LPC260DSC LPC260DSF LPC260QBF8RB9 LPC260RSC LPC260RSF35
LPC260RSF8RB9 LPC270QBC LPC

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : On November 17, 2020, OCC received clarification to the report delivery dates and began to identify those vehicles involved at the known manufacturing plants. OCC is still working with Dometic to identify deliveries in which Dometic cannot assign a physical address, which means OCC does not know which manufacturing plant(s) other than what is recalled, is affected. At this time, Dometic is working to supply OCC with this information.

On November 18, 2020, OCC received via USPS Mail formal notification to Forest River of Dometic Recall 20E071. OCC is still trying to identify other manufacturing plants received the subject stoves/cooktops.

LEPRECHAUN	LPC200CBF8RB9-215	2020	26
LEPRECHAUN	LPC210QBC	2019	16
LEPRECHAUN	LPC210QBC	2020	20
LEPRECHAUN	LPC210QBF35	2020	4
LEPRECHAUN	LPC210RSC	2019	7
LEPRECHAUN	LPC210RSC	2020	16
LEPRECHAUN	LPC210RSF35	2019	3
LEPRECHAUN	LPC210RSF35	2020	9
LEPRECHAUN	LPC220QBF8RB9	2020	23
LEPRECHAUN	LPC220QBF8RB9-215	2020	94
LEPRECHAUN	LPC220XGC	2020	3
LEPRECHAUN	LPC230CBF8RB9	2020	77
LEPRECHAUN	LPC230FSC	2020	15
LEPRECHAUN	LPC230FSF35	2020	2
LEPRECHAUN	LPC240FSC	2019	5
LEPRECHAUN	LPC240FSC	2020	27
LEPRECHAUN	LPC240FSF	2019	11
LEPRECHAUN	LPC240FSF	2020	16
LEPRECHAUN	LPC260DSC	2019	54
LEPRECHAUN	LPC260DSC	2020	84
LEPRECHAUN	LPC260DSC	2021	1
LEPRECHAUN	LPC260DSF	2019	31
LEPRECHAUN	LPC260DSF	2020	72
LEPRECHAUN	LPC260QBF8RB9	2020	80
LEPRECHAUN	LPC260QBF8RB9	2021	13
LEPRECHAUN	LPC260RSC	2020	2
LEPRECHAUN	LPC260RSF35	2019	3
LEPRECHAUN	LPC260RSF35	2020	1
LEPRECHAUN	LPC260RSF8RB9	2020	60
LEPRECHAUN	LPC270QBC	2019	41
LEPRECHAUN	LPC270QBC	2020	52
LEPRECHAUN	LPC270QBF35	2019	4
LEPRECHAUN	LPC270QBF35	2020	12

Vehicle 9 : 2019-2021 Coachmen Mirada - MDA29FW MDA32SS MDA35BHF MDA35LSF
MDA35OSF

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : On November 17, 2020, OCC received clarification to the report delivery dates and began to identify those vehicles involved at the known manufacturing plants. OCC is still working with Dometic to identify deliveries in which Dometic cannot assign a physical address, which means OCC does not know which manufacturing plant(s) other than what is recalled, is affected. At this time, Dometic is working to supply OCC with this information.

On November 18, 2020, OCC received via USPS Mail formal notification to Forest River of Dometic Recall 20E071. OCC is still trying to identify other manufacturing plants received the subject stoves/cooktops.

MIRADA	MDA29FW	2020	14
MIRADA	MDA32SS	2020	7
MIRADA	MDA35BHF	2020	15
MIRADA	MDA35LSF	2020	1
MIRADA	MDA35OSF	2020	22

Production Dates : AUG 29, 2018 - APR 17, 2020

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 10 : 2019-2021 Forest River Inc. Salem - SMT171RBXL SMT17RKXL SMT19DBXL
SMT230BHXL SMT240BHXL SMT241QBXL SMT24RLXL SMT261BHXL SMT263BHXL
SMT273QBXL SMT282QBXL

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : On November 17, 2020, OCC received clarification to the report delivery dates and began to identify those vehicles involved at the known manufacturing plants. OCC is still working with Dometic to identify deliveries in which Dometic cannot assign a physical address, which means OCC does not know which manufacturing plant(s) other than what is recalled, is affected. At this time, Dometic is working to supply OCC with this information.

On November 18, 2020, OCC received via USPS Mail formal notification to Forest River of Dometic Recall 20E071. OCC is still trying to identify other manufacturing plants received the subject stoves/cooktops.

SALEM SMT171RBXL	2020	48
SALEM SMT17RKXL	2020	1
SALEM SMT19DBXL	2020	40
SALEM SMT230BHXL	2020	9
SALEM SMT240BHXL	2020	37
SALEM SMT241QBXL	2020	25
SALEM SMT24RLXL	2020	46
SALEM SMT261BHXL	2020	49
SALEM SMT263BHXL	2020	67
SALEM SMT273QBXL	2020	66
SALEM SMT282QBXL	2020	15

Production Dates : AUG 29, 2018 - APR 17, 2020

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 11 : 2019-2021 Coachmen Sportscoach - S1A339DS S1A365RB S1A366BH S1A409BG-360

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : On November 17, 2020, OCC received clarification to the report delivery dates and began to identify those vehicles involved at the known manufacturing plants. OCC is still working with Dometic to identify deliveries in which Dometic cannot assign a physical address, which means OCC does not know which manufacturing plant(s) other than what is recalled, is affected. At this time, Dometic is working to supply OCC with this information.

On November 18, 2020, OCC received via USPS Mail formal notification to Forest River of Dometic Recall 20E071. OCC is still trying to identify other manufacturing plants received the subject stoves/cooktops.

SPORTSCOACHS1A339DS	2020	2
SPORTSCOACHS1A365RB	2020	5
SPORTSCOACHS1A366BH	2020	1
SPORTSCOACHS1A409BG-360	2020	1

Production Dates : AUG 29, 2018 - APR 17, 2020

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 12 : 2019-2021 Forest River Inc. Wildwood - WDT171RBXL WDT19DBXL WDT230BXL
WDT240BXL WDT241QBXL WDT24RLXL WDT261BXL WDT263BXL
WDT273QBXL WDT282QBXL

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : On November 17, 2020, OCC received clarification to the report delivery dates and began to identify those vehicles involved at the known manufacturing plants. OCC is still working with Dometic to identify deliveries in which Dometic cannot assign a physical address, which means OCC does not know which manufacturing plant(s) other than what is recalled, is affected. At this time, Dometic is working to supply OCC with this information.

On November 18, 2020, OCC received via USPS Mail formal notification to Forest River of Dometic Recall 20E071. OCC is still trying to identify other manufacturing plants received the subject stoves/cooktops.

WILDWOOD	WDT171RBXL	2020	39
WILDWOOD	WDT19DBXL	2020	32
WILDWOOD	WDT230BXL	2020	4
WILDWOOD	WDT240BXL	2020	36
WILDWOOD	WDT241QBXL	2020	37
WILDWOOD	WDT24RLXL	2020	91
WILDWOOD	WDT261BXL	2020	50
WILDWOOD	WDT263BXL	2020	54
WILDWOOD	WDT273QBXL	2020	51
WILDWOOD	WDT282QBXL	2020	19

Production Dates : AUG 29, 2018 - APR 17, 2020

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : As Per Dometic's recall 20E071 - The defect enunciation can occur in a mobile environment, such as a recreational vehicle or marine vessel, when, generally after an install or usage period of 3-6 months, the installer, occupant, or user of the appliance smells gas and apparently attempts to tighten the securement bolts that hold one or more of the stove saddle valves in place and sealed to the manifold. This action may result in the overtightening of the securement bolt for the saddle valve which may cause damage to the O-ring seal between the saddle valve and the manifold resulting in a continuous gas leak that is readily detectable from the smell.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The overtightening of the saddle valve securement bolt onto the manifold of

Description of the Safety Risk : the stove may cause a gas leak which may ignite and cause a fire. Dometic has had one instance of ignition and damage to the piezo igniter and one control knob, although the ignition was contained within the stove enclosure. There has been no damage to adjacent or surrounding combustible materials. A gas leak can lead to the risk of fire, property damage, injury, or possible death.

Description of the Cause : Dometic has not determined the cause of these leaks but is continuing to gather facts on the potential defect and will forward additional relevant information as it becomes available.

Identification of Any Warning that can Occur : The smell gas fumes are indicative of the identified leak.

Involved Components :

Component Name 1 : Saddle Valve and Manifold

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Dometic Corporation

Address : 5155 Verdant Dr.
Elkhart INDIANA 46516

Country : United States

Chronology :

On November 9, 2020, Forest River's Office of Corporate Compliance ("OCC") reviewed NHTSA's weekly recall alert email and found that a recall from another recreational vehicle manufacturer had been filed in conjunction with Dometic recall 20E071. The same day, OCC sent a request for more information to Dometic to ascertain if any Forest River manufacturing plants are affected by Dometics recall.

On November 12, 2020, OCC sent an email request to all purchasing agents within Forest River to try and find if any manufacturing division used the Dometic recalled stoves/cooktops.

On November 13, 2020, OCC sent another request to Dometic to find out if any Forest River manufacturing plants are affected by the Dometic recall. OCC received a response the same day with sales records from Dometic.

On November 16, 2020, OCC contacted Dometic to clarify the report delivery dates that was given to OCC, such as the delivery dates and certain manufacturing delivery locations.

On November 17, 2020, OCC received clarification to the report delivery dates and began to identify those vehicles involved at the known manufacturing plants. OCC is still working with Dometic to identify deliveries in which Dometic cannot assign a physical address, which means OCC does not know which manufacturing plant (s) other than what is recalled, is affected. At this time, Dometic is working to supply OCC with this information.

On November 19, 2020, OCC received via USPS Mail formal notification to Forest River of Dometic Recall 20E071. OCC is still trying to identify other manufacturing plants received the subject stoves/cooktops.

On November 23, 2020, Forest River filed the recall with NHTSA and Trans Canada - Forest River is still working with Dometic to ensure the affected vehicles reported are correct.

Description of Remedy :

Description of Remedy Program : Dometic has NOT yet identified a proposed remedy or remedies designed to mitigate the defect but will advise NHTSA of such remedy or remedies at the time they are identified. Dometic will further initiate a remedy campaign on the R1731, R21231 and S31 recreational vehicle stoves and will participate in remedy campaigns for the R1731, R2131 and S31 products launched by Original Equipment Manufacturers who have purchased, sold and distributed these products.

What is the Dometic Customer Service Address and Phone Number?

Manufacturer Name : Dometic Corporation

Address : 5155 Verdant Dr.

Elkhart IN 46516

Company phone : 574-293-0681

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : JAN 02, 2021 - JAN 02, 2021

Planned Owner Notification Date : JAN 02, 2021 - JAN 02, 2021

* NR - Not Reported