

PROCESS REMINDER FOR SERVICE BULLETIN 587 REAR BRAKE BLEED - ROCKET 3 R, ROCKET 3 GT, ROCKET 3 TFC



Notice Information

| | |
|--------------|---|
| Ref | 19277 |
| Posted Date: | |
| Posted To: | General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Aftersales Manager, Service Leader / Advisor, Accounts / Admin |
| Subject: | Service/Technical |

TOL NOTICE (US&CA) – August 23, 2021

TOL Ref. # 19277-SVC

PROCESS REMINDER FOR SERVICE BULLETIN 587 REAR BRAKE BLEED - ROCKET 3 R, ROCKET 3 GT, ROCKET 3 TFC

When carrying out Service Bulletin 587 regarding the Rear Brake Bleed on the Rocket 3 R, Rocket 3 GT, or Rocket 3 TFC it is vital that the full procedure detailed in the Service Bulletin document is followed precisely. **Note that the detailed 7-step process must be carried out TWICE resulting in 14 total steps.**

VIN Range of Models Affected: VIN 971477 to VIN AD1122

Please refer to the attached SB587 document ([EN](#)) ([FR](#)) on TOL for full instructions.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.