The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Manufacturer Name :	Forest River, Inc.
Submission Date :	DEC 10, 2020
NHTSA Recall No. :	20V-763
Manufacturer Recall No. :	51-1256

Manufacturer Information :

Manufacturer Name : Forest River, Inc. Address : 55470 CR 1 P.O. Box 3030 Elkhart IN 46515-3030 Company phone : 1-800-348-7440

Vehicle Information :

Vehicle Type : Body Style : Power Train :	TRAILERS OTHER NR The plant was able to determin	POD Travel Trailer Recreational Ve ne the affected vehicles by using pro produced will have securement ac ermination plumbing in place.	oduction records.
Production Dates : VIN Range 1 :	APR 28, 2017 - FEB 11, 2020 Begin : NR	End: NR	☐ Not sequential

Description of Defect :

Description of the Defect :	On certain vehicles, the sewer termination bracket may fail causing the plumbing to become detached from the bracket.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	If the plumbing were to become detached from the bracket, this could cause the sewer termination plumbing to drag on the ground or become completely detached from the vehicle causing a crash, property damage and/or injury.
Description of the Cause :	On certain vehicles, the securement of the bracket was insufficient to hold the length of the sewer termination plumbing in place.
Identification of Any Warning that can Occur :	Visual signs of loose sewer termination plumbing.



Number of potentially involved : 2,818 Estimated percentage with defect : 100 %

Population :

20V-763

Part 573 Safety Recall Report

20V-763

Involved Components :

Component Name 1: NR

Component Description : NR

Component Part Number: NR

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology :

9/21/2020 – Received VOQ 11354675 indicating a problem with the sewer pipe.

9/24/2020 - OCC opened an investigation to review plant installation and securement processes and inspection of units.

11/11/2020 – Processes, inspections and analysis completed.

11/13/2020 – Recall Committee met and requested further analysis of data due to no clear trend of year and make.

12/4/2020 – Investigation and scope complete. Corporate Recall Committee voted to recall.

Description of Remedy :

Description of Remedy Program :	Forest River will provide all parts and labor free of charge to consumer to add securement to the sewer termination pipe. An authorized Forest River Dealer or Service Center will need to perform the repair.What is the Forest River Customer Service Phone Number? (574) 642-3119 Option 2

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

5 1	Securement will be installed in addition to the existing bracket
from Recalled Component :	
Identify How/When Recall Condition was Corrected in Production :	November 2019, an additional securement strap was added to the plumbing
Recall Schedule :	
Recall Schedule : Description of Recall Schedule :	Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.
	suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573