



## IMPORTANT SAFETY RECALL NOTICE

1/6/2021

NO. 2020-01

This notice applies to your Skeeter Boat/Trailer Package (Serial # STE#####A###)

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Skeeter Products, Inc. has determined that a defect may exist in certain 2020 Skeeter Built trailers which relates to motor vehicle safety. Our records indicate you own the affected trailer shown above.

On the affected trailers, the slider pin(s) which secure the brake caliper assembly in position over the brake rotor could become loose under normal operating conditions {allowing the brake caliper not to function as designed} and cause loss of control that could result in a crash.

To inspect/correct this defect, your authorized Skeeter dealer will tighten or replace the slider pin(s). This procedure could take up to one (1) hour. However, your Skeeter dealer may need to keep your Boat/Trailer package longer depending upon their current service schedule. **There will be no charge to you for this procedure.**

Please contact your Skeeter dealer to arrange an immediate appointment to have this procedure performed. At that time, your dealer will advise you of the length of time they will need to keep your boat/trailer package for this service. Remember to take this letter with you when you drop off your Skeeter boat/trailer package.

**You should not tow your affected boat/trailer package shown above, other than to the dealer for inspection, until this service has been performed.**

If you are unable to return to the Skeeter dealer who sold you the boat/trailer package, this service can be performed by any authorized Skeeter dealer. For the name of a Skeeter dealer near you, please call 903-984-0541 or visit the Skeeter website at [www.skeeterboats.com](http://www.skeeterboats.com).

If you have had this service performed before receiving this letter, you may be entitled to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this repair. For more information, please contact Skeeter Customer Relations at 903-984-0541.

Federal regulations require that any Boat/Trailer lessor receiving this recall notice must forward a copy of this letter to lessee within 10 days.

If after contacting your Skeeter dealership, you have questions or concerns which the dealership is unable to answer please contact Skeeter at the following address: SKEETER Products, One Skeeter Road, Kilgore, TX 75662 Or call, 903-984-0541.

If, after contacting Skeeter Customer Relations, you are still not satisfied that we have done our best to remedy the situation without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the Auto Safety Hotline at 1-800-327-4236 (TTY: 1-800-424-9153); or go to [www.safercar.gov](http://www.safercar.gov). Refer to this recall number (2020-01).

If you have sold your Boat/Trailer package to another party, please call us at 1-903-984-0541 with the name and address of the new owner, along with the Serial Number shown to the right of your name on the address label above.

We apologize for any inconvenience that we may have caused you, but we are sincerely concerned about your safety and continued satisfaction with our products.

Thank you for giving your attention to this important matter.

Sincerely,

Robert Young  
Customer Relations Manager  
SKEETER Products  
903-983-5646  
[Robert\\_young@yamaha-motor.com](mailto:Robert_young@yamaha-motor.com)