OMB Control No.: 2127-0004

Recall Quarterly Report

20V-784

Manufacturer Name: Aston Martin The Americas

NHTSA Recall No. / MFR Recall No.: 20V-784 /RA-30-1471

Recall Subject: Vehicles Assembled Without Headliner Foam Blocks

Owner Notification Beginning Date: JAN 15, 2021

Owner Notification End Date: JAN 15, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 14, 2021	2021-1	151	66	1	0

This Document Last Updated: APR 15, 2021

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012).

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.