TOPIC	TYPE	RECALL CODE	QUESTION	ANSWER			
			What vehicles	Country	Beginning Model Year	Ending Model Year	Vehicle
Safety Recall 69BC	Safety Recall	69BC	are included in Safety Recall 69BC?	USA	2012	2014	BEETLE
				USA	2012	2014	BEETLE CONVERTIBLE
			What is the safety concern for Safety Recall 69BC?	The driver's side air bag inflator may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, high temperatures, and high temperature cycling. An inflator explosion may result in sharp metal fragments striking the driver or other occupants resulting in serious injury or death. To correct this defect, your authorized Volkswagen dealer will replace the driver frontal airbag. This work will take about an hour to complete and will be performed for you free of charge. Please keep in mind that your dealer may need additional time for the preparation of the repair, as well as to accommodate their daily workshop schedule. Parts are available now and repairs have begun. Please contact your authorized Volkswagen dealer without delay to schedule this recall repair. To set up an appointment online, please visit www.vw.com/find-a-dealer.			
			What is the repair for Safety Recall 69BC? When will the repair for Safety Recall 69BC be available?				