• A remedy is available for your vehicle.



IMPORTANT SAFETY RECALL 2021030014

This notice applies to your vehicle, VIN:

Replace Wheel-Hub Cap

NHTSA Recall #20V800

May, 2021



Dear Mercedes-Benz Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has decided that a defect which relates to motor vehicle safety exists in certain Model Year ("MY") 2019-2020 AMG GT-Class 4-Door Coupe vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

What is the CONCERN?

In certain MY 2019-2020 AMG GT-Class Coupe vehicles, the wheel hub caps that display the Mercedes-Benz emblem might not have been manufactured according to current production specifications. The fastening clip mechanism on the caps might not withstand induced stresses while driving, and could detach from the wheel-hub. If the wheel-hub caps detach from the vehicle while driving, they could become a road hazard for following traffic, which could increase the risk of a crash or injury for other road users.

What will your DEALER DO?

An authorized Mercedes-Benz dealer will replace the wheel-hub caps on the affected vehicles. This service will be provided free of charge. We are dedicated to always delivering the best customer experience, and respect for your time is a top priority. While the minimum repair time can be less than half an hour, your dealer can provide you with a better estimate of the overall time for this service visit. As a matter of normal service process, an authorized Mercedes-Benz dealer will also check for other repair measures which might be applicable to your vehicle and this may increase the required working time.

What should YOU DO?



To find the most convenient authorized Mercedes-Benz dealer from your smartphone, scar the QR code to the left.

For additional information and to schedule an appointment, please contact your preferred authorized Mercedes-Benz dealer at your earliest convenience. To locate authorized dealers see www.MBUSA.com/recall. Please mention you are scheduling an appointment to replace the wheel-hub caps under Recall Campaign # 2021030014. You may be asked for your 17-digit Vehicle Identification Number (VIN) which for your convenience is located above your name at the top of this letter.

Impacts from COVID-19: Your health and safety remain our top priority. The Mercedes-Benz dealerships remaining open for recall repairs and service are closely following the guidelines set forth by the CDC. Free Mobile Repair at your home or business as well as vehicle pick-up and delivery may be available. Your preferred authorized Mercedes-Benz dealer can confirm availability.

Information for Owners

In the event that you are no longer the vehicle owner, or have had a change of address, please complete the reverse side and return the updated information in the enclosed envelope.

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

A VIN-based recall lookup tool on our MBUSA.com website offers a search feature that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. See **www.mbusa.com/recall**. Should you have any questions or encounter any difficulty regarding this Recall Campaign, please contact an authorized Mercedes-Benz dealer. If for any reason a dealer is unable to remedy your situation, we are always happy to hear from you. Please contact us at 1-(800) FOR-MERCEDES (1-800-367-6372).

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to https://www.safercar.gov.

We apologize for any inconvenience this situation may cause you.

Sincerely,

Mercedes-Benz USA

IMPORTANT

If for any reason YOU NO LONGER OWN THIS VEHICLE OR have a CHANGE OF ADDRESS, please COMPLETE THE SECTION BELOW, place in the ENCLOSED ENVELOPE, and DROP IN ANY MAIL BOX. If possible, provide the name and address of the present owner

so t	hat w	e ma	ay co	ontac	t the	em.																							
	☐ LEASE, VEHICLE RETURNED													□ SOLD □ STOLEN □ OTHER															
	NEW OWNER INFORMATION															☐ MY NEW NAME OR ADDRESS IS:													
La	st Nar	ne, Fi	irst N	lame	1	1		1	1		<u>I</u>	1	1	<u> </u>	1	1	1		1		1	1	<u>I</u>		l	<u> </u>	<u></u>		l
Stı	Street											1	Apt											<u>I</u>					
City													<u> </u>	State ZI								ZI	P						
En	nail Ad	ldres	S				I	1	1	1	1			1	ı	I		1		I	1		1	I			<u> </u>	<u> </u>	I
															1														
Phone (numbers only)															_	Mobi	le (n	<u>l</u> umbe	ers o	nly)							<u> </u>		
Date						-	Sign	atur	 е																				

**** PLEASE DO NOT DETACH. RETURN COMPLETE LETTER ****
DO NOT USE THE ENCLOSED ENVELOPE FOR OTHER CORRESPONDENCE