## **Recall Quarterly Report**

20V-806

Manufacturer Name : Daimler Trucks North America, LLC NHTSA Recall No. / MFR Recall No. : 20V-806 /FL-871 Recall Subject : Hydraulic Caliper Tie Bar May Be Loose Owner Notification Beginning Date : FEB 18, 2021 Owner Notification End Date: MAR 17, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 14, 2021	2021-1	278	164	0	0

This Document Last Updated : APR 28, 2021

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.