75

Part 573 Safety Recall Report

21E-008

Manufacturer Name : BIGFOOT INDUSTRIES, INC. Submission Date : FEB 04, 2021

Manufacturer Recall No. : NR

Manufacturer Information :

Manufacturer Name : BIGFOOT INDUSTRIES, INC.

Address: 4114 CROZIER ROAD ARMSTRONG BRITISH COLUMBIA, CANADA 00 VOE 1B6 Company phone : 250-546-2155

Equipment Information :

Brand / Trade 1:	Bigfoot RV
Model :	15C8.2, 15C9.5FS, 15C9.5FR, 25C9.4, 25C9.6, 25C10.4, 25C10.6
Part No. :	1731
Size :	3 BURNERS
Function :	NR
Descriptive Information :	Please See Dometic recall 20E71
Production Dates :	JUL 15, 2019 - DEC 23, 2020

Description of Defect :

Description of the Defect :	Recall 20E71, Dometic Corporation has identified the Model 1731 Ovens and Stoves have a potential defect. A gas leak may occur at the joint between the gas saddle valve for the burners and the manifold connection.
FMVSS 1 :	302 - Flammability of interior materials
FMVSS 2 :	NR
Description of the Safety Risk :	There is a risk of a gas leak which may cause an explosion and or fire.
Description of the Cause :	Dometic believes these leaks are caused by field adjustments when overtightening a securement bolt for the saddle valve to the manifold
Identification of Any Warning that can Occur :	There could be the smell of Gas and or a Propane detector alarm go into alarm.

Involved Components :

The information contained in this report was submitted pursuant to 49 CFR §573



Number of potentially involved :

Estimated percentage with defect : 99 %

Population :

NHTSA Recall No.: 21E-008

Part 573 Safety Recall Report

Component Name : Oven and Stove Component Description : Cooking Appliance Component Part Number : R1731

Supplier Identification :

Component Manufacturer

Name : Dometic Corporation Address : 5115 Verdant Dr. Indiana 46516 Country : United States

Chronology:

Please see Dometic recall 20E71

Description of Remedy :

Description of Remedy Program :	Dometic is providing a kit to be installed in each defective oven and stove affected. This kit will be installed free of Charge by an Authorized Dometic repair center.
How Remedy Component Differs from Recalled Component :	Replacement Kit will exchange parts, Dometic to provide further info.
Identify How/When Recall Condition was Corrected in Production :	NR

Recall Schedule :

Description of Recall Schedule :	NR
Planned Dealer Notification Date :	FEB 15, 2021 - FEB 26, 2021
Planned Owner Notification Date :	FEB 22, 2021 - MAR 05, 2021

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

The information contained in this report was submitted pursuant to 49 CFR §573

21E-008

Part 573 Safety Recall Report

Name :NRAddress :NRNRNRCountry :NRCompany Phone :NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573

21E-008