

Part 573 Safety Recall Report

21E-053

Manufacturer Name : Shenzen YouCheng Dianzishangwu Youxiangg**Submission Date :** AUG 09, 2021**NHTSA Recall No. :** 21E-053**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Shenzen YouCheng Dianzishangwu Youxiangg
Address : Shenzhen Longhuaqu Fuchengjiedao
 Zhanggeshequzhanggelu
 355hao2dong101 Shenzhen 00
 518000
Company phone : 19924524665

Number of potentially involved : 3,000
Estimated percentage with defect : 100 %

Equipment Information :**Brand / Trade 1 :** Sealight**Model :** S1H11**Part No. :** AHDS1H11-E**Size :** NR**Function :** NR**Descriptive Information :** Aftermarket LED Headlight bulbs**Production Dates :** JAN 01, 2018 - DEC 31, 2020**Description of Noncompliance :**

Description of the Noncompliance : These bulbs fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment**FMVSS 2 :** NR

Description of the Safety Risk : These bulbs create excessive glare or brightness to oncoming traffic, that increases the risk of a crash. Owners can contact Sealight customer service at youchengdianzi2021@163.com.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name : Seallight LED Headlight Bulbs

Component Description : Aftermarket LED Headlight Bulbs

Component Part Number : AHDS1H11-E

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

With headlight S1-H11 installed in the assembly, and the light intensity was tested according to the standard SAE FMVSS NO.108. The light intensity of the following 3 test points: 0.6D-1.3R, 0.86D-V and 1.5D-2R was lower than the specified lower limit, while the rest of test points met the requirements of the standard. It can be seen that the risk of S1-H11 affecting the driver coming from the opposite car is small.

Description of Remedy :

Description of Remedy Program : We will notify owners and will replace the LED bulbs with Halogen bulbs, free of charge. Owners can contact Seallight customer service at youchengdianzi2021@163.com.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : The recall report was submitted on June 16th, 2021. Since June 25th, our car owners began to receive recall notices. From June 25th to July 31st, we received about 752 car owners' feedback on the demand for recall. We solved the customer's problem by sending replacement of original halogen bulbs or refunding the car owners. Considering that some car owners did not contact us in the first time after receiving the recall email,

we will follow up with the same standard for those owners who contacted us after July after being verified to be within the recall scope. We have always maintained a very rigorous and responsible attitude towards the recall report.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : JUN 25, 2021 - JUL 31, 2021

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

* NR - Not Reported