

**Recall Quarterly Report****21E-061**

**Manufacturer Name :** Guangzhou Yorkim Trading Co., Ltd  
**NHTSA Recall No. / MFR Recall No. :** 21E-061 /  
**Recall Subject :** Headlight Bulbs are Too Bright/FMVSS 108  
**Owner Notification Beginning Date :** JUL 06, 2021  
**Owner Notification End Date:**



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JAN 31, 2022	2021-4	3,000	0	0	0
1	SEP 28, 2021	2021-3	3,000	0	0	0

This Document Last Updated : JAN 31, 2022

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.