



## BES CM2450 EV101B systems for NHTSA Recall 21E-083:

System Control Module Serial Number	Vehicle Model	Vehicle Identification Number (VIN)
83000		



# \*\*\* IMPORTANT SAFETY RECALL\*\*\* NHTSA Recall No. 21E-083 Cummins Campaign #C2491

October 8, 2021

#### Dear Cummins Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Cummins Inc. has decided that a defect which relates to motor vehicle safety exists in certain BES CM2450 EV101B electric drivetrain systems that were manufactured between November 1, 2020 and May 21, 2021.

This notice applies to the electric drivetrain systems in your vehicle(s) listed on the enclosed table.

#### WHAT IS THE PROBLEM?

The high voltage shutdown override switch may not function, without warning the driver, when a system shutdown fault occurs.

If the vehicle shuts down sooner than the driver expects, the driver may have insufficient opportunity to move the vehicle to a safe location, increasing the risk of a crash.

### WHAT ARE WE DOING ABOUT THE PROBLEM?

Cummins has released field Safety Campaign #C2491 "BES CM2450 EV101B Shutdown Override Safety Campaign" to correct this condition by updating a parameter in the System Control Module. This campaign is currently available at Cummins Distributors and authorized Warranty Dealers. The repair will be completed free of charge and most applications will require approximately 1 hour to complete.

### WHAT SHOULD YOU DO?

Cummins recommends that you notify drivers that the high voltage shutdown override switch may not function until the repair is completed.

Contact the nearest Cummins Distributor or authorized Warranty Dealer to arrange to have this campaign performed on your drivetrain system. The distributor or dealer will work with you to schedule the best date to complete this repair.

If you have questions or concerns about this recall, please contact your local Cummins Distributor or authorized warranty dealer. You may also contact Cummins Care at 1-800- CUMMINS (1-800-286-6467), or visit our website at care.cummins.com.



If you have a complaint relative to this recall, you may report it to the following:

Administrator National Highway Traffic Safety Administration 1200 New Jersey Avenue, SE Washington, DC 20590

You may also call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.

If you have not registered your Cummins product, please complete the enclosed registration card or register your product at <a href="https://prodreg.cummins.com/prodreg/#/webform/contactInfo">https://prodreg.cummins.com/prodreg/#/webform/contactInfo</a>.

If you are no longer the owner of the vehicle(s) listed on the enclosed table, please forward this notice to the new owner or provide the new owner's contact information to Cummins so that we can notify them of this recall.

Federal law requires vehicle lessors receiving this recall notice to forward a copy of this notice to the lessee within ten (10) days. Also, it is a violation of Federal law for a dealer to deliver a new vehicle or equipment covered by this recall notice under a sale or lease until the defect has been remedied.

Cummins is taking this action in the interest of safety and satisfaction with our products. We apologize for any inconvenience and thank you for your attention to this matter.

Sincerely,

Campaign Administrator Cummins Inc.