

IMPORTANT SAFETY RECALL

Trailer Reverse Steering Control Module

Y85/NHTSA 21E-096

Dear [Name],

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

FCA US has decided that certain Trailer Reverse Steering Control Modules (TRSCMs) fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) No. 111 - Rearview mirrors.

- Mopar Trailer Reverse Steering Control Module 68423566AE
- Mopar Trailer Reverse Steering Control Module 68423566AF

It is extremely important to take steps now to repair your vehicle to ensure the safety of you and your passengers.

YOUR SCHEDULING OPTIONS

- 1. RECOMMENDED OPTION**
Call your authorized Chrysler / Dodge / Jeep® / RAM Dealership
- 2. Call the FCA Recall Assistance Center at 1-800-853-1403. An agent can confirm part availability and help schedule an appointment**
- 3. Visit recalls.mopar.com or download the Mopar Owner's Companion App.**

Get access to recall notifications, locate your nearest dealer, and more through this website or Mopar Owner's Companion App. You will be asked to provide your Vehicle Identification Number (VIN) to protect and verify your identity.

DEALERSHIP INSTRUCTIONS

Please reference Safety Recall Y85.

WHY DOES MY VEHICLE NEED REPAIRS?

FCA records indicate that you may have purchased or had installed a Mopar replacement TRSCM for your vehicle ^[1]. Some of the above TRSCMs may prevent the rearview image from displaying under certain conditions. An Electronic Throttle Control warning indicator may also be illuminated in the instrument panel cluster. If installed in a vehicle, the vehicle operator will notice that the rearview image is not displayed if attempting to reference the image while backing. **If this warning is not heeded, backing without verifying it is safe to do so could lead to an increased risk of injury to people outside the vehicle.**

The condition described above does not comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 571.111 S6.2.6 which requires that "The rear visibility system default to the rearview image being visible, and meet the requirements of FMVSS 571.111 S6.2.1 (field of view) and S6.2.2 (image size) at the beginning of each backing event, regardless of any modifications to the field of view that the driver had previously selected."

HOW DO I RESOLVE THIS IMPORTANT SAFETY ISSUE?

FCA US is conducting a voluntary equipment safety recall on all affected parts to repurchase, exchange, or update suspect TRSCMs. **Be sure to bring the TRSCM module with this letter to your dealership.** Your vehicle may also be included in the Y80 Safety Recall for repair of the same TRSCM. To do this, your dealer will update the TRSCM software. The estimated repair time is 30 minutes. In addition, your dealer will require your vehicle for proper check-in, preparation, and check-out during your visit, which may require more time. Your time is important to us, so we recommend that you schedule a service appointment to minimize your inconvenience. Please bring this letter with you to your dealership.

**TO SCHEDULE YOUR FREE REPAIR,
CALL YOUR CHRYSLER, DODGE, JEEP OR RAM DEALER TODAY**

WHAT IF I ALREADY PAID TO HAVE THIS REPAIR COMPLETED?

If you have already experienced this specific condition and have paid to have it repaired, you may visit www.fcarecallreimbursement.com to submit your reimbursement request online. ^[3] Once we receive and verify the required documents, reimbursement will be sent to you within 60 days. If you have had previous repairs performed and/or already received reimbursement, you may still need to have the recall repair performed.

We apologize for any inconvenience, but are sincerely concerned about your safety. Thank you for your attention to this important matter.

Customer Assistance/Field Operations
FCA US LLC



Mr. Mrs. Customer
1234 Main Street
Hometown, MI 48371

[1] If you no longer own this vehicle, please help us update our records. Call the FCA Recall Assistance Center at 1-800-853-1403 to update your information.

[2] If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, DC 20590, or you can call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to safercar.gov.

[3] You can also mail in your original receipts and proof of payment to the following address for reimbursement consideration: FCA Customer Assistance, P.O. Box 21-8004, Auburn Hills, MI 48321-8007, Attention: Recall Reimbursement.

Note to lessors receiving this recall notice: Federal regulation requires that you forward this recall notice to the lessee within 10 days.