U.S. Department of Transportation National Highway Traffic Safety Administration

February 24, 2021

Mr. Harald Morgenstern Manager NHTSA Compliance Continental Tire the Americas, LLC 1830 MacMillan Park Drive Fort Mill, SC 29707 Continental Tire the Americas, LLC

Subject: Tire Failure may Cause Sudden Air Loss

Dear Mr. Morgenstern:

This letter serves to acknowledge Continental Tire the Americas, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BARUM/BRAVURIS 3 HM/215/55 R 16 97H CONTINENTAL/4X4 CONTACT/255/50 R 19 107H CONTINENTAL/CONTIPROCONTACT/205/65 R 16 95H CONTINENTAL/CONTIPROCONTACT/215/55 R 16 97H CONTINENTAL/CONTIPROCONTACT/235/40 R 19 92H CONTINENTAL/CONTIPROCONTACT/235/45 R 19 95H CONTINENTAL/CONTIPROCONTACT/235/55 R 17 99H CONTINENTAL/CONTIPROCONTACT/P215/60 R 16 94T CONTINENTAL/CONTIPROCONTACT SSR/245/45 R 18 100V CONTINENTAL/CONTISPORTCONTACT 5/255/45 R 20 101W CONTINENTAL/CONTITRAC/LT275/65 R 18 123/120S CONTINENTAL/CONTROLCONTACT TOUR A/S PLUS/225/55 R 17 97H CONTINENTAL/CROSSCONTACT LX/225/65 R 17 102T CONTINENTAL/CROSSCONTACT LX SPORT/235/65 R 18 106H CONTINENTAL/CROSSCONTACT LX SPORT/245/50R20 102H CONTINENTAL/CROSSCONTACT LX SPORT/245/60 R 18 105T CONTINENTAL/CROSSCONTACT LX SPORT/255/50 R 19 107H CONTINENTAL/CROSSCONTACT LX SPORT/255/50 R 20 105T CONTINENTAL/CROSSCONTACT LX SPORT/255/50 ZR 19 107W CONTINENTAL/CROSSCONTACT LX SPORT/255/50R20 105T CONTINENTAL/CROSSCONTACT LX SPORT/265/45 R 20 108H CONTINENTAL/CROSSCONTACT LX SPORT/265/45 R 21 104V CONTINENTAL/CROSSCONTACT LX20/235/60 R 18 107H CONTINENTAL/CROSSCONTACT LX20/255/55 R 20 107H CONTINENTAL/CROSSCONTACT LX20/P275/55 R 20 111S CONTINENTAL/CROSSCONTACT LX25/245/50 R 20 102H CONTINENTAL/CROSSCONTACT LX25/255/50 R 19 107H CONTINENTAL/EXTREMECONTACT DWS06/245/45 R 19 98Y CONTINENTAL/PREMIUMCONTACT 6/315/30 R 22 107Y CONTINENTAL/PREMIUMCONTACT 6 SSR/275/40 R 22 107Y



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150CL 21T-001

CONTINENTAL/PROCONTACT TX/215/60 R 16 95H CONTINENTAL/PROCONTACT TX/225/55 R 18 98H CONTINENTAL/PROCONTACT TX/225/60 R 18 100H CONTINENTAL/PROCONTACT TX/235/60 R 18 103H CONTINENTAL/PROCONTACT TX/P205/55 R 16 89V CONTINENTAL/PURECONTACT LS/205/55 R 16 91V CONTINENTAL/SURECONTACT LX/265/65 R 18 114T CONTINENTAL/TERRAINCONTACT A/T/275/55 R 20 113T GENERAL TIRE/ALTIMAX RT43/225/60 R 17 99H GENERAL TIRE/ALTIMAX RT43/225/60 R 18 100H GENERAL TIRE/ALTIMAX RT43/235/55R19 105V GENERAL TIRE/ALTIMAX RT43/245/45 R 20 99V GENERAL TIRE/ALTIMAX RT43/245/50 R 20 105H GENERAL TIRE/AMERITRAC TR/P265/70 R 17 113H GENERAL TIRE/EXCLAIM HPX A/S/205/50 R 17 93V GENERAL TIRE/EXCLAIM HPX A/S/215/55 R 17 94V GENERAL TIRE/EXCLAIM HPX A/S/225/50 R 17 94V GENERAL TIRE/EXCLAIM HPX A/S/235/55 R 17 99W GENERAL TIRE/GRABBER A/TX/265/70 R 17 115T GENERAL TIRE/GRABBER A/TX/35 X 12.50 R 18 123R GENERAL TIRE/GRABBER A/TX/LT265/70 R 17 121/118S GENERAL TIRE/GRABBER A/TX/LT265/70 R 18 124/121S GENERAL TIRE/GRABBER A/TX/LT275/60 R 20 119/116S GENERAL TIRE/GRABBER A/TX/LT275/65 R 18 123/120R GENERAL TIRE/GRABBER A/TX/LT275/70 R 18 125/122R GENERAL TIRE/GRABBER A/TX/LT285/70 R 17 121/118S GENERAL TIRE/GRABBER APT/255/75 R 17 115T GENERAL TIRE/GRABBER APT/265/75 R 16 116T GENERAL TIRE/GRABBER APT/P275/70 R 18 116S GENERAL TIRE/GRABBER ARCTIC LT/LT245/70 R 17 119/116R GENERAL TIRE/GRABBER AT2/265/70R16 112S GENERAL TIRE/GRABBER HD/LT245/75 R 16 120/116S GENERAL TIRE/GRABBER HTS/235/65 R 17 108H GENERAL TIRE/GRABBER HTS/255/70 R 17 112S GENERAL TIRE/GRABBER HTS/265/70 R 18 116S GENERAL TIRE/GRABBER HTS/LT225/75 R 16 115/112S GENERAL TIRE/GRABBER HTS/P245/70 R 17 108S GENERAL TIRE/GRABBER HTS/P255/70 R 17 110S GENERAL TIRE/GRABBER HTS60/225/75 R 16 104S GENERAL TIRE/GRABBER HTS60/235/65 R 18 106T GENERAL TIRE/GRABBER HTS60/245/65 R 17 107T GENERAL TIRE/GRABBER HTS60/275/60 R 20 115S GENERAL TIRE/GRABBER HTS60/LT245/75 R 16 120/116S GENERAL TIRE/GRABBER STX/245/65 R 17 107T GENERAL TIRE/GRABBER STX/265/70 R 17 115S GENERAL TIRE/GRABBER STX2/275/60 R 20 115S GENERAL TIRE/GRABBER X3/35 X 12.50 R 20 121Q GENERAL TIRE/RELIATREK HT/245/65 R 17 107H

Mfr's Report Date: February 15, 2021

NHTSA Campaign Number: 21T-001

Components: TIRES



Potential Number of Units Affected: 93,959

Problem Description:

Continental Tire the Americas, LLC. (Continental Tire) is recalling certain Continental, General, and Barum brand tires sold as original or replacement equipment. The affected tires were cured for too long during production.

Consequence:

Over cured tires may develop a break in the sidewall resulting in sudden air loss or a belt edge separation which could lead to a tread/ belt loss. Either condition can cause a loss of vehicle control, increasing the risk of a crash.

Remedy:

Continental Tire will notify the owners that purchased the tires as replacement equipment. Various vehicle manufacturers will conduct recalls for vehicles equipped with these tires at the time of purchase. The tires will be inspected to verify that they are affected, and will be replaced as necessary, free of charge. The recall is expected to begin April 5, 2021. Owners may contact Continental Tire customer service at 1-888-799-2168.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Continental Tire the Americas, LLC's contact for this recall will be Choon Lee who may be reached by email at choon.lee@dot.gov. We look forward to working with you.

Sincerely,

Alae Anoly

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

