

Recall Quarterly Report**21V-008**

Manufacturer Name : Braun Northwest
NHTSA Recall No. / MFR Recall No. : 21V-008 /
Recall Subject : Brake Line Routing May Cause Wear and Fluid Leak
Owner Notification Beginning Date : JUN 08, 2020
Owner Notification End Date: JUN 11, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 06, 2021	2020-2	23	23	0	0

This Document Last Updated : APR 13, 2021

Definitions :

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.