

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS6035  
URGENT - DISTRIBUTE IMMEDIATELY

Date: January 24, 2022

Subject: REVISION – N212346640-01 – Safety Recall  
Rear Suspension Toe Link May Break  
Customer Letter Added

Models: 2010 – 2013 Buick LaCrosse  
2012 – 2013 Buick Regal  
2013 Chevrolet Malibu

To: All General Motors Dealers

Bulletin N212346640-01 has been revised to include a copy of the customer notification letter. Please discard all copies of bulletin N212346640.

**Customer Letter Mailing**

The customer letter mailing will begin on January 27, 2022.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS