

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager  
Freightliner Dealers– U.S. and Canada  
Western Star and Sterling Dealers– U.S. and Canada  
FCCC Dealers– U.S. and Canada  
Thomas Built Buses Dealers– U.S. and Canada  
Direct Warranty Customers – U.S. and Canada  
Detroit Diesel Distributors  
Export Distributors

Daimler Trucks North America LLC

**WARRANTY CAMPAIGNS DEPARTMENT**  
P.O. Box 4090 800-547-0712  
Portland, Oregon 97208-4090

If you have questions about this Letter, please submit your inquiry on the Web using the [WSC Link on DTNAConnect](#)

REF #: ICI22-016  
Effective: 03/22/2022  
Release: 03/22/2022

**SUBJECT: FL856 – Superseded by FL917 ~ FCCC Chassis Rear PDM**

This letter is to inform you that Recall FL856 ~ FCCC Chassis Rear PDM has been superseded by Recall FL917 ~ FCCC Chassis Rear PDM. **FL917 will be visible to dealers on 3/24/22.**

- Last repair date for FL856 is 3/23/22
- First repair date for FL917 is 3/24/22

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC Link on DTNAConnect.

REF #: ICI22-016  
En vigueur: 22/03/2022  
Sortie: 22/03/2022

**OBJET: FL856 – Remplacé par FL917 ~ PDM arrière du châssis FCCC**

Cette lettre est pour vous informer que Recall FL856 ~ FCCC Chassis Rear PDM a été remplacé par Recall FL917 ~ PDM arrière du châssis FCCC. Le FL917 sera visible par les concessionnaires le 24/03/22.

- La dernière date de réparation pour FL856 est le 23/03/22
- La première date de réparation pour FL917 est le 24/03/22

Si vous avez des questions ou avez besoin de plus amples informations, contactez le service des campagnes de garantie en soumettant une demande via le lien WSC sur DTNAConnect