

U.S. Department of Transportation

National Highway Traffic Safety Administration

February 11, 2021

Mr. Antonio Mole Daimler Vans USA, LLC 8501 Palmetto Commerce Pkwy Ladson, SC 29456 1200 New Jersey Avenue SE Washington, DC 20590

NEF-150MR 21V-042

Subject: Electronic Stability Control Unit Malfunction

Dear Mr. Mole:

This letter serves to acknowledge Daimler Vans USA, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FREIGHTLINER/SPRINTER 3500/2012-2018 MERCEDES-BENZ/SPRINTER 3500/2012-2018

Mfr's Report Date: February 3, 2021

NHTSA Campaign Number: 21V-042

Components:

ELECTRONIC STABILITY CONTROL: CONTROL MODULE

Potential Number of Units Affected: 48.667

Problem Description:

Daimler Vans USA, LLC (DVUSA) is recalling certain 2012-2018 Mercedes Benz Sprinter 3500 and Freightliner Sprinter 3500 vehicles upfitted into campers or recreational vehicles. The Electronic Stability Control (ESC) unit may become disabled on these vehicles.

Consequence:

If ESC becomes disabled, vehicle driving stability may be impacted under certain driving conditions, increasing the risk of a crash.

Remedy

DVUSA will notify owners, and dealers will replace the rear-wheel speed sensor with a more robust sensor, free of charge. The recall is expected to begin February 22, 2021. Owners may contact DVUSA customer service at 1-877-762-8267. DVUSA's number for this recall is NC3DREZAHA.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:



You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigations

Enforcement

