IMPORTANT SAFETY RECALL

IMPORTANT SAFETY RECALL NOTICE 2021070007

This notice applies to your vehicle

VIN:

Replace Rear Wheel Speed Sensors NHTSA Recall ID: 21V042

August, 2021



- · A remedy is available for your vehicle.
- Schedule an appointment with your authorized Mercedes-Benz dealer as soon as possible.
- This repair will be provided free of charge.

Dear Mercedes-Benz Sprinter Owner:

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz Sprinter vans, has decided that a defect which relates to motor vehicle safety exists in certain Model Year ("MY") 2012 - 2018 Mercedes-Benz Sprinter vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

What is the issue?



On certain MY2012–2018 5-ton Sprinter vehicles that were upfitted into campers or recreational vehicles ("RVs"), one or more of the rear-wheel speed sensors may experience an electrical failure, which potentially could lead to a disablement of the Electronic Stability Control ("ESP") control unit functions. If ESP control unit functions are disabled, vehicle driving stability may be impacted under certain driving conditions, which could increase the risk of a crash.



What will your Mercedes-Benz Dealer do?

An authorized Mercedes-Benz Sprinter dealer will replace the rear-wheel speed sensors with new sensors.

Steps to take.



For additional information and to schedule an appointment, please contact your preferred authorized Mercedes-Benz Sprinter dealer at your earliest convenience. To locate nearest Mercedes-Benz dealers visit https://www.mbvans.com or call 1-800 FOR-MERCEDES (1-800-367-6372).

Please mention you are scheduling an appointment to replace rear wheel speed sensors under Recall Campaign #2021070007

This could take approximately 1 hour. This service will be provided free of charge. You may be asked for your 17-digit Vehicle Identification Number (VIN) which for your convenience is located above your name at the top of this letter.

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

A VIN-based recall lookup tool on our website offers a search feature that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. See www.mbvans.com/en/recall-information.

Should you have any questions, please contact your authorized Mercedes-Benz dealer. We apologize for any inconvenience this may have caused and look forward to taking care of this important safety issue immediately.

Sincerely, Mercedes-Benz USA

Mercedes-Benz USA, LLC

A Daimler AG Company One Mercedes-Benz Drive Sandy Springs, GA 30328 Phone: (770) 705-0600



IMPORTANT SAFETY RECALL

Additional Information for Owners:

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to https://www.safercar.gov.

IMPORTANT

	IIII OKIAKI	VIN:	
If for any reason YOU NO LONGER OWN THIS VEHION ENCLOSED ENVELOPE, and DROP IN ANY MAIL BOX them.			
 □ EXPORTED □ LEASE, VEHICLE RETURNED □ SCRAPPED □ SOLD □ STOLEN □ OTHER 			
□ NEW OWNER INFORMATION OR□ MY NEW NAME OR ADDRESS IS:			
Last Name, First Name			
Street			Apt
City		State	ZIP
Email Address			
Phone (numbers only)	Mobile	(numbers only)	

Signature

Mercedes-Benz USA, LLC

A Daimler AG Company One Mercedes-Benz Drive Sandy Springs, GA 30328 Phone: (770) 705-0600

Date

