

ROYAL ENFIELD

*****AUTO**MIXED AADC 530 P5 C5



IMPORTANT SAFETY RECALL

This notice applies to your vehicle, VIN [REDACTED]
Model: ROYAL ENFI INT 650
March 15, 2021
Royal Enfield Recall No. SC 14
NHTSA Recall No. 21V-045

Dear Royal Enfield Motorcycle Owner,

This notice is sent to you in accordance with the requirements of the National Traffic Motor and Vehicle Safety Act. Royal Enfield of North America LTD has decided that a defect which relates to motor vehicle safety exists on certain 2019 ROYAL ENFI INT 650 motorcycles. This is to inform you that your vehicle has been included in a voluntary safety recall campaign. We would like to ensure your safety, and that your riding experience is not compromised. According to our records, you are the owner of the vehicle mentioned above.

Reason for this action:

We have determined when motorcycles are used on roads on which salt has been applied during the winter for melting ice, corrosion of the brake callipers can occur. This can cause the brakes to drag and braking performance could be affected or become ineffective, possibly resulting in a crash. 2019 ROYAL ENFI INT 650 motorcycles that were likely being used in such conditions may be impacted.

Royal Enfield North America LTD is focused on delivering an exceptional ownership experience and requires your attention in addressing this matter.

Owner required actions:

At your earliest convenience, we request that you call an authorized Royal Enfield dealer to schedule a service appointment to replace the front and rear brake calipers. **IMPORTANT: Should you choose to ride your motorcycle before this safety recall service has been completed, to reduce the risk associated with this condition, we recommend that you evaluate your motorcycle BEFORE each ride per the following procedure:**

With your bike in neutral -

1. Fully depress rear brake pedal and release.
2. Fully squeeze front brake lever and release.
3. Slightly rock the motorcycle back and forth to ensure that brakes have released normally and increased brake drag is not present.

NOTE: If increased brake drag from either the front or rear brake is noted, your motorcycle may be exhibiting the recall condition.