

Part 573 Safety Recall Report

21V-049

Manufacturer Name : Jayco, Inc.**Submission Date :** FEB 04, 2021**NHTSA Recall No. :** 21V-049**Manufacturer Recall No. :** 9901563**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

Population :

Number of potentially involved : NR

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2021-2021 Fifth Wheel Eagle

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : 2021 Eagle Fifth Wheel Models WD WA - produced Oct - Dec 2020- while we know the units affected, specific unit serial numbers / totals are not available at this time. will edit 573 upon receipt

Production Dates : DEC 22, 2020 - JAN 18, 2021

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : There was an Engineering change around October 6 2020 that added a 4 ¼” spring hanger when it should have been a 5 ¼” hanger reducing the tire clearance.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Reduced tire clearance can result in tire contact, increasing the risk of tire blow out which could cause handling issues increasing the risk of an accident.

Description of the Cause : Engineering error on print / specifications

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

1-23-21 Operations reported Incident to Compliance - noting error - corrections made to units on site

1-25-21 - Incident discussed at WIRC and elevated to CPAC

1-25-21 - CPAC reviewed all details of the incident and escalated to Safety Steering Committee with recommendation of Recall

1-28-21 - SSC reviewed all details and agreed that Safety Recall was required.

Description of Remedy :

Description of Remedy Program : Jayco Dealer will install the correct 5 1/4 spring hangers.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : ECN to correct the error -> Jayco drawing 0.122.286 revision D was revised to move curbside front slideout ram forward 6 7/8" to be centered above center spring hanger.

☒ The center spring hanger stayed at 4 1/4".

☒ ECN MEJ388

Recall Schedule :

Description of Recall Schedule : Jayco will release recall based on parts availability

Planned Dealer Notification Date : MAR 15, 2021 - MAR 15, 2021

Planned Owner Notification Date : MAR 15, 2021 - MAR 15, 2021

* NR - Not Reported