

U.S. Department of Transportation

National Highway Traffic Safety Administration

March 8, 2021

Mr. Nick Kahl Director Customer Service Seagrave Fire Apparatus, LLC 105 E 12th Street Clintonville, WI 54919 Seagrave Fire Apparatus, LLC

Subject: Power Steering Filter Tightened Incorrectly

Dear Mr. Kahl:

This letter serves to acknowledge Seagrave Fire Apparatus, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

SEAGRAVE/ATTACKER/2019-2021 SEAGRAVE/CAPITAL/2019-2021

Mfr's Report Date: February 23, 2021

NHTSA Campaign Number: 21V-105

Components:

STEERING:HYDRAULIC POWER ASSIST:HOSE, PIPING, AND CONNECTIONS STEERING:HYDRAULIC POWER ASSIST:POWER STEERING FLUID

Potential Number of Units Affected: 54

Problem Description:

Seagrave Fire Apparatus, LLC (Seagrave) is recalling certain 2019-2021 Attacker and Capitol vehicles equipped with a Cummins X12 engine. The spin-on power steering filter may not have been tightened correctly, which can cause it to loosen and leak power steering fluid.

Consequence:

A power steering fluid leak may result in the loss of power steering assist, increasing the risk of a crash.

Remedy:

Seagrave will notify owners, and dealers will inspect the power steering filter, and retighten or replace it as necessary, free of charge. The recall is expected to begin April 12, 2021. Owners may contact Seagrave customer service at 1-800-777-5360.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

NEF-107MR

21V-105

Please ensure the following requirements are met:

An identification and description of the risk to motor vehicle safety reasonably related to the defect or noncompliance (49 CFR 573.6 (c)(5)). All filings should state an increased risk of either a crash, injury or fire.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Seagrave Fire Apparatus, LLC's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

