TOPIC	TYPE	RECAL L CODE	QUESTION	ANSWER			
			What vehicles are included in	Country	Beginning Model Year	Ending Model Year	Vehicle
Safety Recall 44R1	Safety Recall	44R1	Safety Recall 44R1?	USA	2018	2019	ATLAS
				USA	2020	2020	ATLAS CROSS SPORT
			What is the safety concern for Safety Recall 44R1? What is the repair for Safety Recall 44R1?	Vehicles included in this recall may have received potentially affected "overcured" Continental brand tires out of specific production lots. The potentially affected tires may experience a carcass break in the sidewall with sudden air loss, or could develop a belt edge separation that could lead to a partial or full tread/belt loss. Sudden loss of tire air pressure without warning may cause loss of vehicle control, increasing the risk of a crash. To correct this defect, your authorized Volkswagen dealer will inspect and, if necessary, replace affected tire(s). The inspection will take about a half an hour. If tire(s) replacement is needed, it can take up to two hours. This work will be performed for you free of charge. Please keep in mind that your dealer may need additional time for the preparation of the repair, as well as to accommodate their daily workshop schedule. Parts are available now and repairs have begun. Please contact your authorized Volkswagen dealer without delay to schedule this recall repair. To set up an appointment online, please visit www.vw.com/find-a-dealer.			
			When will the repair for Safety Recall 44R1 be available?				