IMPORTANT SAFETY RECALL


IMPORTANT SAFETY RECALL FINAL NOTICE 2021050005

This notice applies to your vehicle

VIN: 123456

Install Additional Retaining Ring on Brake Pedal Bracket
NHTSA Recall ID: 21V152

June, 2021



- A remedy is available for your vehicle.
- Schedule an appointment with your authorized Mercedes-Benz dealer as soon as possible.
- This repair will be provided free of charge.

Dear Freightliner Sprinter Owner:

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Freightliner Sprinter vans, has decided that a defect which relates to motor vehicle safety exists in certain Model Year 2019-2020 Freightliner Sprinter vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

What is the issue?



MBAG has determined that on certain Sprinter vehicles, the retaining washer on the bolt that connects the brake pedal to its bearing block could come loose. If the retaining washer were to come loose, over time it could detach from the bolt, and in the worst case and with ongoing use of the brake pedal, the bolt might separate from the bearing block on one side. If this were to occur, the brake lamp switch could become continuously activated even when the brake pedal is not pressed. If the brake lamps are continuously illuminated, it would not be possible for following traffic to determine the braking intention of the vehicle, which could increase the risk of a crash.



What will your Freightliner Dealer do?

An authorized Freightliner dealer will install an additional retaining ring on the bearing bracket of the brake pedal.

Steps to take.



For additional information and to schedule an appointment, please contact your preferred Freightliner Sprinter dealer at your earliest convenience.

To locate authorized Freightliner dealers, please visit https://www.freightlinersprinterusa.com/freightliner/shopping-tools/find-a-dealer or call 1-877-762-8267


Please mention you are scheduling an appointment to inspect power steering hose clamps under Recall Campaign # 2021050005.

This could take approximately 1hr and 30 minutes. This service will be provided free of charge. You may be asked for your 17-digit Vehicle Identification Number (VIN) which for your convenience is located above your name at the top of this letter.

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

Please visit <u>www.freightlinersprinterusa.com/freightliner/owners-resources/recall</u>. Should you have any questions or encounter any difficulty regarding this Recall Campaign, please contact an authorized Freightliner dealer. A VIN-based recall lookup tool on our website now offers a search feature that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed.

Sincerely,
Daimler Vans USA



A Daimler AG Company One Mercedes-Benz Drive Sandy Springs, GA 30328 Phone: (770) 705-0600



IMPORTANT SAFETY RECALL

Additional Information for Owners:

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to https://www.safercar.gov.

												IN	ИРС)RTA	AN ⁻	Т					٧	/IN:					123	456		
If for ENCL them	OSEC																		-									-		
	EAS CRA SOLE STOL	SE, V APPE O LEN	EHIC	CLE F	RETU	JRNI	ED			_																				
□ r		ow	/NEF	R INF	FOR	MAT	ION																							
) ا 🗆	or Viy i	NEW	NA	ME (OR A	ADDI	RESS	S IS:																						
Last	Nam	ie, Fir	rst Na	ame			1	1	l .				1				1													
																												T		
Stre	et								<u> </u>				1				1										Apt			
													Ι														T	T	T -	
City																						9	State	<u> </u>	_	ZIP		1		
		1		1	1	1	1	1	1	1	1		1	1			1							1	$\overline{}$		$\overline{}$	$\overline{}$		
																									<u> </u>	\perp	<u> </u>	<u> </u>		
Ema	il Ad	dress	;																											
Pho	ne (n	umb	ers o	nly)		I	I	I				I	ı	1	ו	Mobil	e (nı	ımbe	ers o	only)									_1	

Signature



Date