



Publication Number: ID0695200

Publication Date: March 2021

Safety Notice

Affected Models	S4S trailers associated with FX20 machines See list of affected VINs on next page
Attention	Dealership Owners, Managers, Parts and Service Managers
What Dealer Should Do	<ol style="list-style-type: none">1. Read the attached customer notice.2. Check safety notification search tool on Dealer Central to see a list of units in your area.3. Order kits to update machines in dealer inventory and those in your area.4. Use instructions on following pages to update affected machines.
Parts Required	190-2688 reflector kit
Estimated Repair Time	30 minutes
Compensation	Parts, labor and mileage. Labor code: SER-LBR4
Dealership Notes	<p>URGENT: Please perform this update as soon as possible in the interest of safety. Ditch Witch requests that you update all machines in your area by 09/30/2021.</p> <p>A notification will be mailed to owners of affected models in two weeks. Please note “What You Should Do” section of the attached customer notice. If you have any questions, contact the Ditch Witch® Product Support Group.</p>

Affected VINs

1DSB321WXM1700327	1DSB321W2L1700319	1DSB321W7K1700721	1DSB141W7J1701139
1DSB321W8M1700326	1DSB321W0L1700318	1DSB141W5K1701156	1DSB141W3J1701137
1DSB321W6M1700325	1DSB321W9L1700317	1DSB141W7K1701157	1DSB141W6J1701133
1DSB321W2M1700323	1DSB321W7L1700316	1DSB141W1K1701154	1DSB141W8J1701134
1DSB321W4M1700324	1DSB321W5L1700315	1DSB141W3K1701155	1DSB141W1J1701136
1DSB321W9M1700321	1DSB321W3L1700314	1DSB321W5K1700720	1DSB141WXJ1701135
1DSB321W0M1700322	1DSB321W1L1700313	1DSB321W9K1700719	1DSB141W4J1701132
1DSB321W7M1700320	1DSB321W8L1700311	1DSB321W5K1700717	1DSB141W2J1701131
1DSB321W0M1700319	1DSB321WXL1700312	1DSB321W3K1700716	1DSB141W4J1701129
1DSB321W7M1700317	1DSB321W6L1700310	1DSB321W7K1700718	1DSB141W0J1701130
1DSB321W9M1700318	1DSB321WXL1700309	1DSB321W1K1700715	1DSB141W1J1701122
1DSB321W5M1700316	1DSB321W6L1700307	1DSB321W8K1700713	1DSB141WXJ1701121
1DSB321W3M1700315	1DSB321W8L1700308	1DSB321W6K1700712	1DSB141W2J1701128
1DSB321W1M1700314	1DSB321W4L1700306	1DSB321W XK1700714	1DSB141W7J1701125
1DSB321W8M1700312	1DSB321W0L1700304	1DSB321W4K1700711	1DSB141W9J1701126
1DSB321WXM1700313	1DSB321W2L1700305	1DSB321W6K1700709	1DSB141W0J1701127
1DSB321W6M1700311	1DSB321W7L1700302	1DSB321W2K1700710	1DSB141W3J1701123
1DSB321W4M1700310	1DSB321W9L1700303	1DSB321W2K1700707	1DSB141W5J1701124
1DSB321W8M1700309	1DSB321W5L1700301	1DSB321W4K1700708	1DSB141W8J1701120
1DSB321W6M1700308	1DSB321W4K1700742	1DSB321W9K1700705	1DSB141WXJ1701118
1DSB321W2M1700306	1DSB321W2K1700741	1DSB321W0K1700706	1DSB141W8J1701117
1DSB321W4M1700307	1DSB321W0K1700740	1DSB321W1K1700701	1DSB141W1J1701119
1DSB321W0M1700305	1DSB321W4K1700739	1DSB321W5K1700703	1DSB141W5H1701117
1DSB321W9M1700304	1DSB321W2K1700738	1DSB321W7K1700704	1DSB141W4J1701115
1DSB321W5M1700302	1DSB321W0K1700737	1DSB321W3K1700702	1DSB141W6J1701116
1DSB321W7M1700303	1DSB321W9K1700736	1DSB141WXJ1701152	1DSB141W2J1701114
1DSB321W3M1700301	1DSB321W7K1700735	1DSB141W1J1701153	1DSB141W0J1701113
1DSB321W5L1700332	1DSB321W5K1700734	1DSB141W8J1701151	1DSB141W9J1701112
1DSB321W3L1700331	1DSB321W3K1700733	1DSB141W6J1701150	1DSB141W5J1701110
1DSB321W1L1700330	1DSB321W1K1700732	1DSB141WXJ1701149	1DSB141W7J1701111
1DSB321W3L1700328	1DSB321W XK1700731	1DSB141W8J1701148	1DSB141W7J1701108
1DSB321W5L1700329	1DSB321W8K1700730	1DSB141W4J1701146	1DSB141W5J1701107
1DSB321W1L1700327	1DSB321W1K1700729	1DSB141W6J1701147	1DSB141W9J1701109
1DSB321W8L1700325	1DSB321W XK1700728	1DSB141W2J1701145	1DSB141W3J1701106
1DSB321WXL1700326	1DSB321W8K1700727	1DSB141W7J1701142	1DSB141W1J1701105
1DSB321W6L1700324	1DSB321W6K1700726	1DSB141W0J1701144	1DSB141WXJ1701104
1DSB321W4L1700323	1DSB321W4K1700725	1DSB141W9J1701143	1DSB141W8J1701103
1DSB321W2L1700322	1DSB321W2K1700724	1DSB141W5J1701141	1DSB141W4J1701101
1DSB321W0L1700321	1DSB321W0K1700723	1DSB141W3J1701140	1DSB141W6J1701102
1DSB321W9L1700320	1DSB321W9K1700722	1DSB141W5J1701138	1DSB141W6H1701143

Affected VINs, continued


1DSB141WXH1701145	1DSB141W5H1701103	1DSB141W8F1701741	1DSB141W9F1701702
1DSB141W8H1701144	1DSB141W3H1701102	1DSB141WXF1701739	1DSB141W9E1701620
1DSB141W4H1701142	1DSB141W1H1701101	1DSB141W6F1701740	1DSB141W6E1701624
1DSB141W2H1701141	1DSB141W2G1701736	1DSB141W6F1701737	1DSB141W5E1701629
1DSB141W0H1701140	1DSB141W0G1701735	1DSB141W0F1701734	1DSB141W1E1701627
1DSB141W4H1701139	1DSB141W9G1701734	1DSB141W4F1701736	1DSB141W3E1701628
1DSB141W2H1701138	1DSB141W7G1701733	1DSB141W2F1701735	1DSB141WXE1701626
1DSB141W0H1701137	1DSB141W3G1701731	1DSB141W9F1701733	1DSB141W8E1701625
1DSB141W7H1701135	1DSB141W5G1701732	1DSB141W5F1701731	1DSB141W4E1701623
1DSB141W9H1701136	1DSB141W1G1701727	1DSB141W7F1701732	1DSB141W2E1701619
1DSB141W5H1701134	1DSB141W1G1701730	1DSB141W7F1701729	1DSB141W7E1701616
1DSB141W3H1701133	1DSB141W3G1701728	1DSB141W3F1701730	1DSB141W9E1701617
1DSB141W1H1701132	1DSB141W5G1701729	1DSB141W5F1701728	1DSB141W0E1701618
1DSB141WXH1701131	1DSB141W2G1701722	1DSB141W1F1701726	1DSB141W3E1701614
1DSB141W8H1701130	1DSB141W8G1701725	1DSB141W3F1701727	1DSB141W5E1701615
1DSB141W1H1701129	1DSB141W4G1701723	1DSB141WXF1701725	1DSB141W1E1701613
1DSB141WXH1701128	1DSB141W6G1701724	1DSB141W4F1701719	1DSB141W6E1701610
1DSB141W8H1701127	1DSB141WXG1701726	1DSB141W0F1701720	1DSB141WXE1701612
1DSB141W9H1701122	1DSB141W9G1701720	1DSB141W8F1701724	1DSB141W8E1701611
1DSB141W6H1701126	1DSB141W2G1701719	1DSB141W6F1701723	1DSB141WXE1701609
1DSB141W4H1701125	1DSB141W0G1701721	1DSB141W4F1701722	1DSB141W8E1701608
1DSB141W0H1701123	1DSB141W5G1701715	1DSB141W2F1701721	1DSB141W6E1701607
1DSB141W2H1701124	1DSB141W1G1701713	1DSB141W2E1701622	1DSB141W4E1701606
1DSB141W7H1701121	1DSB141W3G1701714	1DSB141W5F1701714	1DSB141W2E1701605
1DSB141W5H1701120	1DSB141W7G1701716	1DSB141W9F1701716	1DSB141W5E1701601
1DSB141W9H1701119	1DSB141W0G1701718	1DSB141W0F1701717	1DSB141W7E1701602
1DSB141W7H1701118	1DSB141W9G1701717	1DSB141W7F1701715	1DSB141W9E1701603
1DSB141W1H1701115	1DSB141WXG1701712	1DSB141W2F1701718	1DSB141W0E1701604
1DSB141W3H1701116	1DSB141W6G1701710	1DSB141W1F1701712	1DSB141W9D1702670
1DSB141WXH1701114	1DSB141WXG1701709	1DSB141W3F1701713	1DSB141W9D1702667
1DSB141W8H1701113	1DSB141W8G1701711	1DSB141WXF1701711	1DSB141W0D1702668
1DSB141W6H1701112	1DSB141W4G1701706	1DSB141W8F1701710	1DSB141W2D1702669
1DSB141W4H1701111	1DSB141W6G1701707	1DSB141W1F1701709	1DSB141W8D1702661
1DSB141W2H1701110	1DSB141W8G1701708	1DSB141W0F1701703	1DSB141W4D1702656
1DSB141W6H1701109	1DSB141W2G1701705	1DSB141W4F1701705	1DSB141W0D1702654
1DSB141W4H1701108	1DSB141W0G1701704	1DSB141W8F1701707	1DSB141W7D1702666
1DSB141W2H1701107	1DSB141W5G1701701	1DSB141W6F1701706	1DSB141W5D1702665
1DSB141W0H1701106	1DSB141W9G1701703	1DSB141WXF1701708	1DSB141W6D1702660
1DSB141W9H1701105	1DSB141W7G1701702	1DSB141W2F1701704	1DSB141W3D1702664
1DSB141W7H1701104	1DSB141W8F1701738	1DSB141W7F1701701	1DSB141WXD1702659

Affected VINs, concluded

1DSB141W6D1702657	1DSB141W7B1702860	1DSB141W5A1700958	1DSB141W081702434
1DSB141WXD1702662	1DSB141W9B1702858	1DSB141W4A1700952	1DSB141W881702438
1DSB141W1D1702663	1DSB141W6B1702848	1DSB141W1A1700956	1DSB141W481702436
1DSB141W2D1702655	1DSB141W7B1702857	1DSB141WXA1700955	1DSB141W681702440
1DSB141W8D1702658	1DSB141W6B1702851	1DSB141W2A1700951	1DSB141W581702445
1DSB141W9D1702653	1DSB141WXB1702853	1DSB141W8A1700954	1DSB141W781702446
1DSB141W7D1702652	1DSB141W1B1702854	1DSB141W6A1700953	1DSB141W581702431
1DSB141W5D1702651	1DSB141W8B1702852	1DSB141W891700982	1DSB141WX81702442
1DSB141WXC1702479	1DSB141WXB1702836	1DSB141W591700972	1DSB141W581702428
1DSB141W6C1702480	1DSB141W8B1702849	1DSB141W491700980	1DSB141WX81702439
1DSB141W8C1702478	1DSB141W4B1702850	1DSB141WX91700983	1DSB141W881702441
1DSB141W7C1702472	1DSB141W4B1702847	1DSB141W391700971	1DSB141W181702426
1DSB141W081702451	1DSB141W2B1702846	1DSB141W791700973	1DSB141W681702437
1DSB141W4C1702476	1DSB141W5B1702842	1DSB141W691700981	1DSB141W281702435
1DSB141W6C1702477	1DSB141W1B1702840	1DSB141W891700979	1DSB141W381702430
1DSB141W2C1702475	1DSB141W7B1702843	1DSB141W291700976	1DSB141W381702427
1DSB141W5C1702468	1DSB141W3B1702841	1DSB141W691700978	
1DSB141W5C1702471	1DSB141W3B1702838	1DSB141W491700977	
1DSB141W9C1702473	1DSB141W2B1702832	1DSB141W091700975	
1DSB141W0C1702474	1DSB141W6B1702834	1DSB141W891700965	
1DSB141W8C1702464	1DSB141W0B1702831	1DSB141W191700967	
1DSB141W6C1702463	1DSB141W8B1702835	1DSB141WX91700966	
1DSB141W3C1702467	1DSB141W4B1702833	1DSB141W691700964	
1DSB141W3C1702470	1DSB141W9B1702830	1DSB141W491700963	
1DSB141W7C1702469	1DSB141W2B1702829	1DSB141W291700962	
1DSB141W1C1702466	1DSB141W0B1702828	1DSB141W091700961	
1DSB141W4C1702462	1DSB141W9B1702827	1DSB141WX91700952	
1DSB141W9C1702456	1DSB141W7B1702826	1DSB141W491700952	
1DSB141WXC1702465	1DSB141W8A1700971	1DSB141W391700954	
1DSB141W2C1702461	1DSB141W6A1700970	1DSB141W191700953	
1DSB141W0C1702460	1DSB141WXA1700969	1DSB141W891700951	
1DSB141W4C1702459	1DSB141W9A1700963	1DSB141W081702448	
1DSB141W2C1702458	1DSB141W0A1700964	1DSB141W981702450	
1DSB141W0C1702457	1DSB141W6A1700967	1DSB141W281702449	
1DSB141W7C1702455	1DSB141W5A1700961	1DSB141W781702429	
1DSB141W1C1702452	1DSB141W2A1700965	1DSB141W781702432	
1DSB141WXC1702451	1DSB141W7A1700962	1DSB141W181702443	
1DSB141W5B1702839	1DSB141W3A1700957	1DSB141W981702447	
1DSB141W5B1702856	1DSB141W3A1700960	1DSB141W381702444	
1DSB141W0B1702859	1DSB141W7A1700959	1DSB141W981702433	

Instructions

1. Clean areas shown with alcohol.
2. Apply yellow reflectors where indicated in first two photos as close to tongue as possible on the side of trailer frame. **Do not apply on tongue.** Reflector will be behind the existing decals (shown in second photo) on one side.
3. Apply red reflectors where indicated in third photo on both sides of trailer. Do not apply reflector over weld on rear-facing locations.



sb053d.jpg



sb052d.jpg

270-8482 amber SAE A DOT reflector, qty 2



sb054d.jpg

270-8483 red SAE A DOT reflector, qty 4