



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

April 2, 2021

Ms. Regina Carto  
Executive Director - Global Safety Field Investigations & Regulatory  
General Motors, LLC  
GM Global Tech Center  
29247 Louis Chevrolet Rd, Floor 2  
Warren, MI 48093

NEF-107DM  
21V-211

**Subject:** Steering Wheel Emblem May Separate

Dear Ms. Carto:

This letter serves to acknowledge General Motors, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

CHEVROLET/CAMARO/2017-2021

**Mfr's Report Date:** March 25, 2021

**NHTSA Campaign Number:** 21V-211

**Components:**

AIR BAGS:FRONTAL

**Potential Number of Units Affected:** 30

**Problem Description:**

General Motors, LLC (GM) is recalling certain 2017-2021 Chevrolet Camaro vehicles. The plastic "Camaro" emblem, located on the steering wheel air bag cover, may separate during deployment of the frontal driver air bag.

**Consequence:**

In the event of a crash, projectiles from deployment of the driver air bag can increase the risk of injury.

**Remedy:**

GM will notify owners, and dealers will replace the frontal driver side air bag module, free of charge. The recall is expected to begin May 10, 2021. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N212327220.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

We have received GM's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.



Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

General Motors, LLC's contact for this recall will be DeMara Magruder who may be reached by email at [demara.magruder@dot.gov](mailto:demara.magruder@dot.gov). We look forward to working with you.

Sincerely,



Alex Ansley  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement