

# Part 573 Safety Recall Report

# 21V-218

**Manufacturer Name :** Winnebago Towable**Submission Date :** MAR 29, 2021**NHTSA Recall No. :** 21V-218**Manufacturer Recall No. :** NR**Manufacturer Information :**

**Manufacturer Name :** Winnebago Towable  
**Address :** 201 14th Street  
 Middlebury IN 46540  
**Company phone :** 825-5250

**Population :**

**Number of potentially involved :** 60  
**Estimated percentage with defect :** 100 %

**Vehicle Information :****Vehicle 1 :** 2020-2020 Winnebago Minnie**Vehicle Type :****Body Style :****Power Train :** NR

**Descriptive Information :** Production Records. Affected units printed out a 15" trire size. Labels that printed out 14" tire size are not included in this recall

**Production Dates :** APR 24, 2020 - APR 29, 2020**VIN Range 1 : Begin :** NR **End :** NR Not sequential**Description of Noncompliance :****Description of the Noncompliance :** Non Compliance to 49CFR 567.4 and 49CFR 571.100

**Noncompliance :** A larger tire size is called out on the "certification label" and the "Tire and Loading Information" label

**FMVSS 1 :** 110 - Tire selection and rims**FMVSS 2 :** NR

**Description of the Safety Risk :** A 15" Tire and Rim bolt pattern will not fit on this axle, in installed a modification would have to be made that could cause a safety risk that could lead to a crash, injury or death

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** NR

**Involved Components :**

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

April 19, 2021 Dealer contacted Winnebago about the label tire size not matching the label.

April 22, 2021 Product Safety was alerted of this issue and determined this is a non-compliance and research for a recall began

April 25, 2021 Submitted 573 report to NHTSA Portal

## Description of Remedy :

Description of Remedy Program : The correct labels and instructions will be sent to the owner along with their notice

How Remedy Component Differs from Recalled Component : The correct label will call our 14" tires -vs- 15"

Identify How/When Recall Condition was Corrected in Production : The program was change to print the correct tire size

## Recall Schedule :

Description of Recall Schedule : TBD - letters will be mailed out within 60 days

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported