



Mercedes-Benz USA, LLC

IMPORTANT SAFETY RECALL

This INTERIM notice applies to your vehicle, VIN: [REDACTED]
Check Tailgate Side Spoilers
NHTSA Recall #21V231

May, 2021

[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]

Dear Mercedes-Benz Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has decided that a defect which relates to motor vehicle safety exists in certain Model Year ("MY") 2020-2021 GLB-Class vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

What is the Concern?

On certain MY2020-2021 GLB-Class vehicles, the side spoilers on the tailgate might not have been installed according to current production specifications. As a result, it is possible that the side spoiler could detach from the vehicle during driving, creating a road hazard which could increase the risk of a crash or injury for other road users.

To remedy this issue, an authorized Mercedes-Benz dealer will check the adhesion of the side spoilers and will replace them, if necessary. Unfortunately, the parts to remedy this are not yet available.

We are working to obtain the necessary parts to correct this condition as quickly as possible. As parts become available, we will send you another letter asking you to take your vehicle to an authorized Mercedes-Benz dealer to have the recall completed free of charge.

Should you have any concerns or questions regarding your vehicle before you receive the next recall letter when parts are available, please contact an authorized Mercedes-Benz dealer. If for any reason a dealer is unable to remedy your situation, we are always happy to hear from you. Please contact us at 1-800-367-6372. A new vehicle identification number (VIN)-based recall lookup tool, on our MBUSA.com website, offers a search function that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. Please visit www.MBUSA.com/recall.

If you are no longer the vehicle owner, or have a change of address, please complete the reverse side of this letter and return the complete letter in the enclosed envelope. If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 days to comply with federal regulations.

If a Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to <http://www.safercar.gov>.

We regret any inconvenience this situation may cause you.

Sincerely,

Mercedes-Benz USA

Mercedes-Benz USA, LLC
A Daimler AG Company
One Mercedes-Benz Drive
Sandy Springs, GA 30328
Phone (770) 705-0600

IMPORTANT

VIN: [REDACTED]

If for any reason YOU NO LONGER OWN THIS VEHICLE OR have a CHANGE OF ADDRESS, please COMPLETE THE SECTION BELOW, place in the ENCLOSED ENVELOPE, and DROP IN ANY MAIL BOX. If possible, provide the name and address of the present owner so that we may contact them.

- EXPORTED
- LEASE, VEHICLE RETURNED
- SCRAPPED
- SOLD
- STOLEN
- OTHER _____

NEW OWNER INFORMATION

MY NEW NAME OR ADDRESS IS:

[Grid for Last Name, First Name]

Last Name, First Name

[Grid for Street]

Street

Apt

[Grid for City, State, ZIP]

City

State

ZIP

[Grid for Email Address]

Email Address

[Grid for Phone (numbers only)]

Phone (numbers only)

[Grid for Mobile (numbers only)]

Mobile (numbers only)

Date

Signature

THANK YOU FOR YOUR COOPERATION