IMPORTANT SAFETY RECALL

IMPORTANT SAFETY RECALL NOTICE 2021050001

This notice applies to your vehicle

VIN:

Reprogram Multifunction Display NHTSA Recall ID: 21V235

May, 2021



Dear Valued Freightliner Owner:

- A remedy is available for your vehicle.
- Schedule an appointment with your authorized Freightliner dealer as soon as possible.
- · This repair will be provided free of charge.

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Freightliner, has decided that the vehicles may not conform to Federal Motor Vehicle Safety Standard(FMVSS) 101 (controls and displays)Our records indicate that your vehicle is included in the affected population of vehicles.

What is the issue?



MBAG determined that on certain VS30 Sprinter vehicles, the degree of illumination in the multifunctional display in the instrument cluster may not be adjustable as specified in Federal Motor Vehicle Safety Standard 101. Affected vehicles that do not meet the illumination adjustment requirements for the instrument cluster do not comply with FMVSS 101, which could increase the risk of a crash if the instrument cluster is too bright for the ambient conditions.



What will your Freightliner Dealer do?

An authorized Freightliner Sprinter dealer will perform a software update for the instrument cluster on the affected vehicles.



Steps to take.

For additional information and to schedule an appointment, please contact your preferred authorized Freightliner Sprinter dealer at your earliest convenience.

To locate authorized dealers see https://www.freightlinersprinterusa.com/freightliner/shopping-tools/find-a-dealer. Please mention you are scheduling an appointment to reprogram of multifunction display under Recall Campaign # 2021050001.

You may be asked for your 17-digit Vehicle Identification Number (VIN) which for your convenience is located above your name at the top of this letter. **This could take less than 30 minutes**. This service will be provided free of charge. You may be asked for your 17-digit Vehicle Identification Number (VIN) which for your convenience is located above your name at the top of this letter.

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

Please visit www.freightlinersprinterusa.com/freightliner/owners-resources/recall. Should you have any questions or encounter any difficulty regarding this Recall Campaign, please contact an authorized Freightliner dealer. A VIN-based recall lookup tool on our website offers a search feature that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed.

Sincerely, Daimler Vans USA



IMPORTANT SAFETY RECALL

Additional Information for Owners:

If an authorized Freightliner dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to https://www.safercar.gov.

IMPORTANT

										110	VIFC	/N 1 <i>F</i>	41 V I						VIN							
	OSED	eason ENVE																								
	EASI SCRA SOLD STOL DTHE NEW DR		HIC)	INF	FOR	 MAT	ION		_																	
Last	Nam	e, Firs	t Na	me					<u> </u>		1					I			<u> </u>	1	<u> </u>				 <u> </u>	
																								<u> </u>		
Stre	et																							Apt		
City																				State	<u> </u>	_	ZIP			
Сіту					1	1	ı	1	ı	ı	ı	1		1		I		ı	1	T	I		-'' 		 1	
Ema	il Add	dress																								
Pho	ne (nı	umber	s or	nly)	<u> </u>	<u> </u>	l	1	 <u> </u>	 <u> </u>		<u> </u>	и М	obile	(nur	nber	s onl	y)	<u> </u>	1	<u> </u>		<u> </u>		 <u> </u>	



	IMPORTANT SAFETY RE	CALL				
Da	ate	Signatu	ıre			

