



**RECREATIONAL VEHICLE
SAFETY RECALL NOTICE**

Safety Recall: 21V-250
Safety Advisory: 21-407
#####, 2021

IMPORTANT SAFETY RECALL



This notice applies to your vehicle: [Redacted]

Dear [Redacted]

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain model 2020-2021 Bullet Travel Trailers. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

Reason for this recall

It has been decided that the vehicles in the recall population have an egress window installed in the bedroom and did not have the correct crank handle installed. If an emergency situation arises the emergency exit may be difficult to open as the current black round knob may impede the ability to open the window, which could result in an increased risk of personal injury.

What we will do

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to remove the existing black round knob and replace it with a narrow crank handle, see page 2 for instructions. We have enclosed the correct narrow crank handle. The service and parts required for this corrective action will be provided at no charge to you.

What we need you to do

Remove the black round knob until you or an authorized dealer can replace it. If you require assistance installing the handle, please make an appointment with your dealer and bring the unit to the dealership and they will install the handle at no cost to you. The labor time to perform this correction is approximately 15 minutes. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

If you have questions

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. Please contact Keystone Customer service if your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you. You may be eligible to receive reimbursement if you paid to have the defect resolved prior to receiving this correspondence. Keystone Customer Service is available toll-free at 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.) Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Thank you for your attention and cooperation in this matter.

Sincerely,

KEYSTONE RV COMPANY

Rick Deisler
Vice President Service Operations
cc: National Highway Traffic Safety Administration (NHTSA)

**PO Box 2000 – Goshen, IN 46527-2000
Phone: (574) 535-2100 – Fax: (574) 535-2199
www.keystonerv.com**



Bullet Egress Window Crank Instructions

The remedy is to replace the black round knob on the bedroom egress window with the narrow crank handle.

REPAIR INSTRUCTIONS



Fig. 1

Step 1

Locate the trailer on a level, flat, hard surface. Chock the wheels.

Step 2

Locate the bedroom egress window. Figure 1



Fig. 2

Step 3

Remove the black round knob and install the narrow crank handle using KRV # 630481- Window - Crank - 3' - Black and an #8-32 x 2" screw. See Figure 2.

